



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013018/AUvf3q2	
			Date: 18/02/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFR 83U	Veh. Inspected	SGR 249Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2003426/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	25/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ACU300059109	Colour	SILVER	
Odometer	151168 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R18	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2020	Inspection Date	26/11/2020	
Survey held at	BEST SOLUTION AUTOCARE PTE LTD 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	