



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2102371
3 ANSON ROAD #16-00	INV Date	08/04/2021
SPRINGLEAF TOWER	Reference	CC3/CTI20013025/Qea3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SHD 6285P
Insured Veh.	SLP 5404J
Claim No.	SNM20D204583
Policy No.	DMPCSNA00172342003
Accident Date	20/11/2020
Inspection Date	23/11/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC3/CTI20013025/Qea3q2 Date: 08/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLP 5404J	Veh. Inspected	SHD 6285P
Policy No.	DMPCSNA00172342003	Coverage (\$)	0.00
Claim No.	SNM20D204583	Excess (\$)	0.00
Assign From		Assign Date	23/11/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS FL	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU003089260	Colour	MAROON
Odometer	114536 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	6 mm
L/H Front Tyre	195/65 R15	DUNLOP	6 mm
R/H Rear Tyre	195/65 R15	DUNLOP	6 mm
L/H Rear Tyre	195/65 R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/11/2020	Inspection Date	23/11/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6285P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	COVER ,RR BUMPER ASSY (DISC 25%)	CRUMPLED	485.60	364.20
1	PAD ,RR BUMPER ,LH & RH 3 (DISC 25%)	NECESSARY	11.00	8.25
1	PAD ,RR BUMPER ,RR & LH 2 (DISC 25%)	NECESSARY	4.00	3.00
1	PAD ,RR BUMPER ,RR & LH 1 (DISC 25%)	NECESSARY	4.00	3.00
1	RETAINER ,RR BUMPER ,RH (DISC 25%)	BROKEN	132.60	99.45
10	CLIPS PIECE ,FRT & RR BUMPER @\$4.50 (DISC 25%)	NECESSARY	4.50	33.75
1	COVER GUARD RR BUMPER LOWER (DISC 25%)	MISSING	22.00	16.50
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	332.70	249.53
1	GUARD ,RR BUMPER ,LOWER (DISC 25%)	CRUMPLED	374.50	280.88
1	COVER ,REAR FLOOR UNDER CENTER (DISC 25%)	CUT	229.90	172.43
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	332.70	-
1	PAD ,RR BUMPER ,CTR	SERVICEABLE	11.00	-
1	SEAL ,RR BUMPER ARM ,RH & LH	SERVICEABLE	11.30	-
1	STOPPER ,RR BUMPER ,RH & LH	SERVICEABLE	4.50	-
1	RETAINER ,RR BUMPER ,LH	SERVICEABLE	132.60	-
1	SEAL ,RR BUMPER ,RH	SERVICEABLE	118.30	-
1	SEAL ,RR BUMPER ,LH	SERVICEABLE	118.30	-
1	GUARD ,RR BUMPER LOWER	SERVICEABLE	374.50	-
1	REAR BUMPER REFLECTOR ASSY ,REFLEX ,RH	SERVICEABLE	39.00	-
1	REAR BUMPER REFLECTOR ASSY ,REFLEX ,LH	SERVICEABLE	39.00	-
1	COVER ,REAR FLOOR UNDER ,RH	SERVICEABLE	175.10	-
1	COVER ,REAR FLOOR UNDER ,LH	SERVICEABLE	241.90	-
1	COVER ,REAR FLOOR UNDER CENTER	SERVICEABLE	229.90	-
1	END PANEL SUB-ASSY ,BODY LOWER BACK	SERVICEABLE	651.00	-
			4,379.90	1,530.99
<b>LABOUR</b>				
PANEL BEATING & BODY WORK .			507.00	200.00
SPRAY PAINT.			918.00	300.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REPLACE SUNDRY PARTS .	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			1,785.00	540.00
	<b>GRAND TOTAL</b>		<b>6,164.90</b>	<b>2,070.99</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,070.99</b>

Report Ref No. CC3/CTI20013025/Qea3q2

**OI SUN PIN**

**Asst. Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SHD 6285P

## INSPECTION








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6285P

RE-INSPECTION








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

