

Section A - Accident Details

Registration Number	SHD6285P
Case Reference Number	TAX/11/20/2041
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LEE SEK HOE
Type of Accident	Head to Rear
Accident Date and Time	20/11/2020 7:20 PM
Accident Reported Date and Time	21/11/2020 10:19 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108880
Special Instruction to ARC, if any	REAR PORTION / CHINA TAIPING - LKK
Prepared Date and Time	23/11/2020 8:23 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$918.00	\$300.00
Total Spare Part Cost	\$3,406.81	\$1,530.99
Total Other Cost	\$360.00	\$40.00
TOTAL COST	\$5,191.81	\$2,070.99 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	24/11/2020 12:09 PM	26/11/2020 2:18 PM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	P/P, Before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2012-0079	Invoice Number	
Quotation Date	08.12.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

22

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$918.00	\$300.00

1544

300

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$40.00

40

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check
		52462-47130	PAD, RR BUMPER, RH & LH, 3	1.00	\$11.00	25.00	\$8.25	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH, 2	1.00	\$4.00	25.00	\$3.00	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH, 1	1.00	\$4.00	25.00	\$3.00	Replace	Replace
		52461-47070	PAD, RR BUMPER, CTR	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.30	0.00	\$0.00	Replace	Check
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.50	0.00	\$0.00	Replace	Check
		52575-47060	RETAINER, RR BUMPER, RH	1.00	\$132.60	25.00	\$99.45	Replace	Replace
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given
		52591-47080	SEAL, RR BUMPER, RH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given
		52592-47080	SEAL, RR BUMPER, LH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		52453-47900	GUARD, RR BUMPER, LOWER	0.00	\$374.50	0.00	\$0.00	Replace	Check
		52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$22.00	25.00	\$16.50	Replace	Replace
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given

CR4

SVC

Nec

Nec

Nec

SVC

SVC

SVC

BR

SVC

SVC

SVC

Nec

SVC

Mis

SVC

SVC

SVC

SVC

SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 08/12/2020

User ID PohSuan

		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given	X
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$175.10	0.00	\$0.00	Replace	Check	X
		58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$241.90	0.00	\$0.00	Replace	Check	X
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Check	X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	X
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Not Given	X
Total					\$3,382.80		\$828.15			

SUC
SUC
SUC
SUC
NEC
short.
SUC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$332.70	25.00	\$249.53	Replace	Replace
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace
		66259-47010	COVER, REAR FLOOR UNDER CENTER	1.00	\$229.90	25.00	\$172.43	Replace	Replace
Total					937.10		702.84		

BT
CRU
cut

1530.99 /
+ 200.00 /
+ 340.00 /

2070.99 /

P/P
\$2,070.99
3 days