

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR20013027/KEA3Q2
Date: 11/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLL1368C	Insured Vehicle No :	SLJ9059C
Date of Loss:	12/02/2019	Nature of Claim:	TP
		Claim No:	9801950265SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL1368C		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGGH654878
Reg. Date:	15/02/2017 (Man. Year: 2016)	Chassis No:	KNAFZ411MH5676939
Colour:	Metallic Grey	Odometer:	76188 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	220.00	230.00	51.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	450.00	220.00	230.00	51.11
+ GST 7.00/7.00% (S\$)	31.50	15.40	16.10	51.11

Nett Amount (S\$)	481.50	235.40	246.10	51.11
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		362.85		

INSPECTION

Date of Assignment: 25/11/2020

Date Inspected: 27/11/2020

Estimated Period of Repair: 1.0 days

Inspected At:

City Auto Pte Ltd (HQ)
 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR AND RESPRAY ACCIDENT PORTIONS	New	450.00	220.00
Gross Labour Cost (S\$)			450.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >