

Rhino Repairs Pte Ltd  
 201600994N  
 160 Sin Ming Drive #03-14  
 Sin Ming Autocity  
 Singapore 575722

Date: 11 May 2019

Make Model:	Toyota DYNA	Engine Capacity	2986 cc
Chassis No:	JTFUF34YX03001227	Year Manufact	24/06/2003
Engine No:	5L5335483	Officer in Charge:	

Vehicle No: GW4063M

Attn:

Fax:

#### PARTS

NO:		QTY	PRICE	Surveyor Approver
1	Tailgate lid	1	\$1,218.60	x repair
2	Tailgate toyota word sticker	1	\$100.00	x nn
3	Tailgate lower latch lever	1	\$157.20	x nn
4	Tailgate lower latch eye	1	\$49.00	x nn
5	Rh taillamp assy	1	\$201.60	x nn
6	Rh taillamp bracket	1	\$51.60	x nn
7	Rear number plate holder	1	\$157.10	x nn
8	Tailgate stopper	1	\$38.60	x nn
9	Tailgate stopper bracket	1	\$69.90	x nn
10	Tailgate dyna sticker	1	\$78.10	x nn
			\$2,121.70	\$ -
Less 25 % discount:			\$530.43	\$ -
Total:			\$2,652.13	\$ -

SPECIAL NET					
1	Tailgate 13 pax sticker ✓	1	\$15.00	nec	
2	Tailgate 70 km/h sticker ✓	1	\$15.00	nec	
3	Rear number plate ✓	1	15 \$45.00	scr	
4	Reverse sensor bracket set X	1	\$24.00	nn	
5	Reverse sensor set X	1 set	\$200.00	nn	
Special Net Total :			\$299.00	\$ -	45

#### LABOUR

1	To check and repair wiring X	30.00	nn
2	To install reverse sensors and check sensing fucni X	60.00	nn
3	Panel Beating charges to remove and repalce, to	800.00	200

4 Spray painting of the affected tailgate, rear deck	800.00	400
6 To apply anti rust chemical on repair and replace	120.00	nn

Total	\$1,810.00	\$ -	600
-------	------------	------	-----

Adjusted Repair Cost

Total Parts:	\$2,951.13	\$ -
Total Labour:	\$1,810.00	\$ -
Total Repair Cost:	\$4,761.13	\$ -

Adjusted Repair (Lump Sum)	645
Estimate Repair Period	6 days
	3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Guo Qiang

82880282