

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFR 787Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RHF DOOR	TO REPAIR SEE LABOUR	2,760.00	-
1	RHF DOOR CHROME	NECESSARY	187.00	187.00
1	RHF DOOR WEATHER-SEAL	SERVICEABLE	256.00	-
1	RHF DOOR WEATHER-SEAL (LOWER)	SERVICEABLE	74.00	-
1	RHR DOOR	TO REPAIR SEE LABOUR	2,410.00	-
1	RHR DOOR CHROME	NECESSARY	170.00	170.00
1	RHR DOOR WEATHER-SEAL	SERVICEABLE	241.00	-
1	RHR DOOR WEATHER-SEAL (LOWER)	SERVICEABLE	60.00	-
1	RHR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-	-35.70
			6,158.00	321.30
	SPECIAL NETT ITEMS			
20	RIVETS (SN)	SERVICEABLE	50.00	ı
			50.00	1
	LABOUR			
	CHECK LIGHTINGS & WIRINGS.		50.00	30.00
	ANTI RUST ON AFFECTED PANELS.		60.00	40.00
	REMOVE & TRANSFER BOTH RH DOOR COMPONENTS.	NOT NECESSARY	250.00	-
	REPLACE DAMAGED PARTS, REPAIR & ALIGN AFFECTED SECTIONS. INCLUSIVE OF THE REPAIR OF RHF DOOR, RHR DOOR, RHR FENDER AND REAR BUMPER.		750.00	400.00
	RESPRAY REPLACEMENT & AFFECTED PARTS.		1,400.00	800.00
			2,510.00	1,270.00
	GRAND TOTAL		8,718.00	1,591.30

RECOMMENDED COST OF LUMP SUM REPAIRS	1,250.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/AIG20011077/Qvd3e2-1





Report Ref No. CS3/AIG20011077/Qvd3e2-1

Jæ

OI SUN PIN

**Asst. Automotive Assessor** 



**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.