



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0413 Fax: 6266-7396  
Email: absolute.app.svcs@gmail.com

### Vehicle Inspection Report

To: Cheong Chee Keong  
C/o: 160 Sin Ming Drive #03-09  
Sin Ming AutoCity (S) 575722

Date of report: 28.10.2020  
Date of request: 12.10.2020  
Date of inspection: 12.10.2020  
Date of accident: 08.10.2020  
Claim type: Third Party Claim

Report No: AAS/2020/223

#### Particulars of affected vehicle:

Registration no: SFR787Y  
Make/Model: Mercedes Benz E250 CGI (A)  
Year of registration: 2009  
Colour: Metallic Silver

Odometer: 137744 km  
Engine Capacity: 1796 cc  
Engine no: 27186030004419  
Chassis no: WDD2120472A080323

#### Condition of tires:

Front Left: 6mm  
Make: Goodyear  
Rear Left: 6mm  
Make: Goodyear

Front Right: 6mm  
Make: Goodyear  
Rear Right: 6mm  
Make: Goodyear

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

#### Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

#### The Assignment

The inspection was conducted at M/s. Kee Yong Automobile Service  
160 Sin Ming Drive #03-09  
Sin Ming AutoCity (S) 575722

#### Assessment

Repairer's estimate:	\$ 8,718.00
Revised estimate:	\$ 7,978.00
Recommended reserve:	\$ 6,400.00 [Lump sum]

Estimated normal duration of repairs : 5 Working days



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0413 Fax: 6266-7396  
Email: absolute.app.svcs@gmail.com

Vehicle No: SFR787Y

Report No: AAS/2020/223

**W/O PREJUDICE**

**Point of impact**

At the RHS portion.

**General description of damages**

The RHF door, RHR door, RHR fender, rear bumper, etc.

Other parts were also found damaged. (See schedule for details)

**Recommendation**

The estimate cost of repair submitted by M/s Kee Yong Automobile Service as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$7,978.00

**Conclusion**

The repairer has agreed to undertake the repair at a lumpsum of SGD \$6,400.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 5 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 36 photographs.

Your Faithfully  
Absolute Appraisal Services Pte Ltd



Nicky Seah  
Automobile Appraiser  
MSAAA / MSMCTA



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SFR787Y

Report No: AAS/2020/223

**Appraisal Schedule**

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	RHF door	1	Dented	\$ 2,760.00	\$ 2,760.00
2	RHF door chrome	1	Dented	\$ 187.00	\$ 187.00
3	RHF door weather-seal	1	Necessary	\$ 256.00	\$ 256.00
4	RHF door weather-seal (lower)	1	Necessary	\$ 74.00	\$ 74.00
5	RHR door	1	Dented	\$ 2,410.00	\$ 2,410.00
6	RHR door chrome	1	Dented	\$ 170.00	\$ 170.00
7	RHR door weather-seal	1	Necessary	\$ 241.00	\$ 241.00
8	RHR door weather-seal (lower)	1	Necessary	\$ 60.00	\$ 60.00
9	RHR fender		Grazed/Repair	-	-
10	Rear bumper		Grazed/Repair	-	-

List total: \$ 6,158.00 \$ 6,158.00

1	Rivets	20	Necessary	\$ 2.50	\$ 50.00	\$ 50.00
---	--------	----	-----------	---------	----------	----------

Special nett total: \$ 50.00 \$ 50.00

Parts Total: \$ 6,208.00 \$ 6,208.00

S/N	Labour Description	Repairer's Est	Revised Est
1	Check lightings & wirings.	\$ 50.00	\$ 30.00
2	Anti rust on affected panels.	\$ 60.00	\$ 40.00
3	Remove & transfer both RH door components.	\$ 250.00	\$ 200.00
4	Replace damaged parts, repair & align affected sections.	\$ 750.00	\$ 500.00
5	Respray replacement & affected parts.	\$ 1,400.00	\$ 1,000.00
Labour Total:		\$ 2,510.00	\$ 1,770.00

Grand Total: \$ 8,718.00 \$ 7,978.00

The final adjusted lump sum amount is \$6,400.00

Under normal circumstances, the repair should be completed within a reasonable period of 5 working days.

36 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.



























