

## **SMRT Accident Vehicle Repair Estimates**

Section A - Accident Details				
Registration Number	SG5961G			
Case Reference Number	BUS/11/20/5012			
Registration Date	20/9/2018			
Company Type	SMRT Buses Ltd			
Make	MAN			
Model	A95			
Name of Driver	Wang Daxiao			
Type of Accident	Side Swipe			
Accident Date and Time	12/11/2020 4:38 PM			
Accident Reported Date and Time	12/11/2020 7:15 PM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number	24108903			
Special Instruction to ARC,if any	ction to ARC,if any SG5961G-LEFT VIEW MIRROR COVER SCRATCHES PA5252L (TP) INSURED WITH NTUC			
Prepared Date and Time	23/11/2020 3:25 PM			
Chassis Number	WMAA95ZZ6JF007562			
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Rep	pair Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$530.00	\$265.00			
Total Spray Cost	\$0.00	\$0.00			
Total Spare Part Cost	\$1,712.97	\$1,712.97			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$2,242.97	\$1,977.97			
Lump Sum Total	\$0.00	\$0.00			
Number of Repair Days	1.0	1.0			
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)			
ARC / Surveyor Sign Off Date	23/11/2020 3:36 PM	24/11/2020 3:58 PM			
Signature	×	SmPn			
Remarks					

Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

## SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 28/12/2020
User ID : CatherineLee



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 28/12/2020
User ID : CatherineLee

			Section	on D - Detail	s of Repair E	stimates			
Part 1 - Labo	ur Works								
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL FRONT VIEW MIRROR LH			\$530.00				\$265.00		
Total Labour			\$530.00				\$265.00		
Part 2 - Spra	y Painting & Pa	nnel Beating Rela	ted Works						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Spray Painting & Panel Beating									
Part 3 - Other	Costs - Accid	ent and Accident	Repair Related Expens	se					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare	Parts / Materi	al Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010159	BODY LH	4001M01- ACCE466	MIRROR,VIEW:FRONT,L H,FOR MAN	1.00	\$1,903.30	10.00	\$1,712.97	Replace	Replace / CRU
Total					\$1,903.30		\$1,712.97		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,712.97
265
1,977.97

P/P \$1,977.97

Idays