

SMRT Accident Vehicle Repair Estimates

	Section A - Accident Details				
Registration Number	SG5597A				
Case Reference Number	BUS/11/20/5022				
Registration Date	9/2/2017				
Company Type	SMRT Buses Ltd				
Make	VOLVO				
Model	B9TL				
Name of Driver	Ramanathan Pannir Selvam				
Type of Accident	Side Swipe				
Accident Date and Time	19/11/2020 10:03 AM				
Accident Reported Date and Time	20/11/2020 2:08 PM				
Is Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	24108899				
Special Instruction to ARC,if any	SG5597A-RIGHT REAR PORTION SHD1564F (TP) INSURED WITH NTUC				
Prepared Date and Time	23/11/2020 9:22 AM				
Chassis Number	YV3S4P928HA180913				
Mileage					
Work Shop					
Repair Completion Date and Time					

	Section B - Summary of Rep	pair Estimates				
Summary of Repair Estimates						
	Quotation from ARC	Adjusted by Surveyor, if applicable				
Total Labour Cost	\$1,060.00	\$530.00				
Total Spray Cost	\$602.00	\$432.00				
Total Spare Part Cost	\$765.63	\$765.63				
Total Other Cost	\$0.00	(\$192.40)				
TOTAL COST	\$2,427.63	\$1,535.23				
Lump Sum Total	\$2,450.00	\$1,550.00				
Number of Repair Days	4.0	2.0				
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)				
ARC / Surveyor Sign Off Date	23/11/2020 4:29 PM	23/11/2020 5:07 PM				
Signature	8	Suntin				
Remarks						

	Section C - Quotation and Accident Invoice Details				
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 06/01/2021
User ID : CatherineLee



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 06/01/2021
User ID : CatherineLee

			Secti	on D - Deta	ails of Repair E	stimates			
Part 1 - Labo	ur Works								
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,060.00				\$530.00		
			\$1,060.00				\$530.00		
Part 2 - Spray	/ Painting & P	Panel Beating Rela	ted Works	'					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY			\$602.00				\$432.00		
Total Spray Painting & Panel Beating			\$602.00				\$432.00		
Part 3 - Other	Costs - Acci	dent and Accident	Repair Related Expens	se					
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Lump Sum Adjustment by Surveyor			\$0.00				(\$192.40)		
Total Other Costs			\$0.00				(\$192.40)		
Part 4 - Spare	Parts / Mater	rial Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PANEL ASSY:FUEL FILL,O/S,FOR VOLVO B9TL	1.00	\$534.38	10.00	\$480.94	Replace	Replace / PC
6012101	Body	A12-01971	O/S SIDE SHEETMETAL PANEL (1)	1.00	\$529.00	10.00	\$476.10	Replace	Replace / DO
Total					\$1,063.38		\$957.04		
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

957.04 530 472 1,919.04 - 206 1,535.23

215 \$1,550 2 days