



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
VINCENT LIM TENG KEAT	Cust No/Name LCV11684/VINCENT LIM TENG KEAT
BLK 109 JALAN BUKIT MERAH	Reg No/Reg Date SM09746D / 13/12/201
#04-1746	Date In/Mileage / 0
SINGAPORE 160109	Chassis No KNAF5416ML5059852
Contact No	Engine No G4FGKH738876
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV11684	CRDVCH	25/11/2020/ 09:22	QUK	282 / Kevin Leong	24790

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR ON FRT RH FENDER, FRT RH DOOR & REAR RH DOOR				600.00
E PNT98000 PAINT WORK ON FRT RH FENDER, FRT RH DOOR & REAR RH DOOR				1050.00
M SUNDRY PERFORM RUST PREVENTION				120.00
A 54900099 CHASSIS ELECTRICAL FREE TEXT				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA				240.00
M SUNDRY SUNDRIES				50.00

Steve CLKK) OD-NM AL  
Excess - 7  
4 days  
By Bol SM  
26/11/20, 4.00pm

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Confirm &amp; accepted by

7% GST on 2210.00 154.70  
Total Payable 2,364.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.