

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 14 Dec 2020

Preliminary Advice

Insured Vehicle No : SLT9045P
TP Vehicle No : SLG4251L
Make : MAZDA 3
Date of Inspection : 26/11/2020
Inspection At : NEW HOCK TECK MOTOR PTE LTD (HQ)
1 KAKI BUKIT AVE 6, BLK C #01-43 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
Accident Date : 25/11/2020
Assignment Date : 25/11/2020
Est. Duration of Repair : 5

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,033.90
Revised Amount	:S\$	3,124.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,124.16
Lump Sum Repair	:S\$	2,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.