



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

25/11/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP MS16
Dense

Accident date: 25/11/2020

Estimated repair cost for vehicle no: SLG4251L MAZDA 3 1.5 A '16

CHASSIS: JM6BM42A8G0346316

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Windscreen Moulding <i>Norm</i>		\$107.00 <i>x</i>
2	1	Front L/H Door Pillar <i>Norm</i>		\$1,035.90 <i>x</i>
3	1	Front L/H Windscreen Pillar <i>Rep</i>		\$862.20 <i>x</i>
4	1	Front L/H Door <i>Dented</i>		\$1,143.00 <i>✓</i>
5	1	Front L/H Door Side Quarter Garnish <i>lt</i>		\$80.00 <i>✓</i>
6	2	Front L/H Door Hinge <i>Norm</i>	\$42.00	\$84.00 <i>x</i>
7	1	Front L/H Door Inner Lock <i>Norm</i>		\$239.10 <i>x</i>
8	1	Front L/H Door Chrome Garnish <i>lt</i>		\$128.60 <i>✓</i>
9	1	Front L/H Door Top Moulding <i>3 mol</i>		\$180.00 <i>+</i>
10	1	Front L/H Door Inner Rubber <i>1 mol</i>		\$142.20 <i>+</i>
11	1	Front L/H Door Glass <i>lt</i>		\$308.60 <i>✓</i>
12	1	Front L/H Door Inner Trim Board <i>3 mol</i>		\$629.10 <i>x</i>
13	8	Front L/H Door Inner Trim Board Clip <i>1 mol</i>	\$6.50	\$52.00 <i>+</i>
14	1	Front L/H Door Window Regulator Motor Assy <i>Norm</i>		\$356.80 <i>x</i>
15	1	Front L/H Side Mirror Assy <i>Distorted</i>		\$682.50 <i>✓</i>
16	1	Rear L/H Door <i>Repair</i>		\$1,258.00 <i>x</i>

Subtotal :- \$5,283.90

2342.70

1874.16

Labour charges

To remove & refit front windscreen	\$120.00	X
To remove & refit cushion & trimboard	\$280.00	X
To remove & refit dashboard	\$350.00	X
To remove & refit front R/H door glass, gear motor, lock, rubber, sticker & trim board	\$300.00	80
To check wiring	\$100.00	30
Tuff kote	\$150.00	40
Panel beating	1250	\$1,200.00 500
Spray painting		\$1,000.00 600

Subtotal :- \$2,750.00

Total:- \$8,033.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3124.16

2/s: 2.5K.

05 Days.

2.5K

05 Days.