



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 109405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Leow Kok Kian (Liao Guojian) BLK 329B ANCHORVALE STREET #06-585 SINGAPORE 54232 Contact No Mobile: 9759883	Cust No/Name /LEOW KOK KIAN (LIAO GUOJIAN) Reg No/Reg Date SLS3374J / 20/09/201 Date In/Mileage / 0 Chassis No KNAFZ411MJ5740249 Engine No G4FGHH678898 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM000081	Cash	25/11/2020/ 13:17		282 / Kevin Leong	24819

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BODY KIT & AFFECTED AREA REPAIR ON REAR RH FENDER				400 160.00
E PNT98000 PAINT WORK ON REAR BUMPER, BODYKIT & REAR RH FENDER				1050 700 1650.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				120 150.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				X 50.00
M SUNDRY PERFORM RUST PREVENTION				40 100.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120 280.00
M SUNDRY SUNDRIES				20 50.00
M COVER-RR BUMPER X R	1.00	688.00	00.00	688.00
M COVER-RR BUMPER,CTR X NM	1.00	315.00	00.00	315.00
M BEAM-RR BUMPER X NM	1.00	318.00	00.00	318.00
M ANTENNA ASSY-SMARTKEY X NM	1.00	69.00	00.00	69.00
M BRACKET-RR BEAM UPR MTG X NM	1.00	3.00	00.00	3.00
M BRACKET-RR BEAM UPR MTG,RH X NM	1.00	3.00	00.00	3.00
M BRACKET-RR BUMPER SIDE MTG,RH X NM	1.00	29.00	00.00	29.00
M K3 BODYKIT / GR	1.00	1177.00	00.00	1177.00

ster (CLKK)
wrt Bel
7/12/20, 11:30 am
4 days
P/P

Confirm & accepted by

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis

Authorized signatory and company stamp

7% GST on Net 5,162.00 5,162.00
Total Payable 5,523.34

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.