

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013039/ETD3E2

Date: 18/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00020352001
Claimant Vehicle No: SBT1881M Insured Vehicle No: SMM9278J
Date of Loss: 19/10/2020 Nature of Claim: TP Claim No: SNM20D203974/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBT1881M
Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UJD2943
Reg. Date: 14/07/2020 (Man. Year: 2019) Chassis No: MMBSTA13AKH004004
Colour: White Odometer: 8279 km
Engine Capacity: 1193 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	106.00	20.00	86.00	81.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	2,780.00	2,670.00	48.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,556.00	2,800.00	2,756.00	49.60
+ GST 7.00/7.00% (S\$)	388.92	196.00	192.92	49.60
Nett Amount (S\$)	5,944.92	2,996.00	2,948.92	49.60

INSPECTION

Date of Assignment: 25/11/2020
Date Inspected: 01/12/2020 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$28.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Mar 2021)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBT1881M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET,RR BUMPER,LH	*Check	28.00 FS	*- FS
2	1		*BRACKET,RR BUMPER,RH	Not Necessary	28.00 FS	*- FS
3	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					106.00	20.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR REAR BUMPER,REPAIR REAR BODY KITS,REPAIR LH REAR FENDER	New	2,560.00	640.00
2	REMOVE AND INSTALL PARKING ASIST	New	80.00	80.00
3	PAINT WORK SPRAY REAR BUMPER,LH REAR FENDER,REAR BODY KITS AND AFFECTED PORTION	New	2,200.00	1,650.00
4	APPLY BODY KITS SEALANT	New	80.00	80.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	50.00	50.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	280.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	200.00	0.00
Gross Labour Cost (\$\$)			5,450.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >