

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 02 Dec 2020

Preliminary Advice

Vehicle No	: GBH7542R	Accident Date	: 16/11/2020
Make	: MERCEDES-BENZ VITO 109	Policy No.	: 0999993880
Assignment Date	: 26/11/2020	Excess	: S\$1,400.00
Date of Inspection	: 26/11/2020	Est. Duration of Repair	: 5
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,344.85	(ESTIMATE \$7,048.35 + SUPPLEMENTARY \$296.50)
Revised Amount	:S\$	5,141.35	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	6,170.73	
Total	:S\$		
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	23,322.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,678.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TO SUPPLY AND PASTE LETTERING ON BONNET WITH INSURED?
KINDLY APPROVE ON SUPPLEMENTARY.