



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 16/11/2020

ESTIMATE

NO : QUOT202011-000066(00)

DATE : 25/11/2020

POLICY NO : 999995580

VEH REG NO : GBH7542R

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : WDF44760323474388

ENGINE NO : R9MA503C052160

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBH7542R

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Air-cleaner assy cra	1	215.00	215.00
			215.00
		Add 10%	21.50
			236.50
LABOUR			
2 To remove and refit air-cleaner assy	1 30	60.00	60.00
			60.00
		TOTAL	S\$ 296.50
		ADD GST @ 7%	20.76
		GRAND TOTAL	S\$ 317.26

SINGAPORE DOLLAR THREE HUNDRED SEVENTEEN AND CENTS TWENTY-SIX ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE