



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI20002103/Qsd3e2-1 Date: 18/12/2020 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 5321A	Veh. Inspected	SMK 2743P	
Policy No.	DMPCSN30717619033	Coverage (\$)	0.00	
Claim No.	SNM20D200521/C01/TANGHL2	Excess (\$)	0.00	
Assign From	ALBERT CHUA	Assign Date	25/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALLION, 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	NZT2603042958	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	HANKOOK	5 mm	
L/H Front Tyre	185/70 R14	HANKOOK	5 mm	
R/H Rear Tyre	185/70 R14	HANKOOK	5 mm	
L/H Rear Tyre	185/70 R14	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/01/2020	Inspection Date	06/02/2020	
Survey held at	BLOCK 10 AMK IND. PARK 2A# 03-13			
Repairer	D'S GRAFFITI CONCEPTS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	