

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP China. NVW2226R2H4058561
Denise.

26 November 2020

QUOTATION FOR ACCIDENT REPAIR OF SLP2120Y VOLKSWAGEN POLO THIRD PARTY INSURER: CHINA TAIPING

<u>S/No.</u>	<u>Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear tailgate <i>Dented</i>	1	\$ 1445.00 ✓
2.	Rear tailgate windscreen moulding <i>new</i>	1	\$ 167.00 ✓
3.	Rear tailgate "logo" emblem with handle <i>cut</i>	1	\$ 556.50 78.
4.	Rear tailgate "TSI" emblem <i>new</i>	1	\$ 62.30 ✓
5.	Rear tailgate mechanism lock <i>new</i>	1	\$ 167.50 +
6.	Rear tailgate lock striker <i>new</i>	1	\$ 65.00 +
7.	Rear tailgate damper L/R <i>new</i>	2	\$ 312.00 +
8.	Rear tailgate wiper motor <i>new</i>	1	\$ 362.50 +
9.	Rear tailgate inner trimboard <i>new</i>	1	\$ 236.00 +
10.	Rear tailgate inner trimboard clip <i>new</i>	8	\$ 44.00 +
11.	Rear tailgate weather strip <i>new</i>	1	\$ 257.50 +
12.	Rear taillamp L/R <i>cut could</i>	2	\$ 760.00 380.
13.	Rear bumper <i>Dented</i>	1	\$ 807.80 ✓
14.	Rear bumper side retainer L/R <i>new</i>	2	\$ 136.00 ✓
15.	Rear bumper side reflector L/R <i>new</i>	2	\$ 170.00 +
16.	Rear bumper reinforcement beam <i>Best</i>	1	\$ 420.30 ✓
17.	Rear bumper no plate lamp L/R <i>new</i>	2	\$ 110.00 +
18.	Rear bumper inner centre bracket <i>could</i>	1	\$ 129.00 ✓
19.	Rear end panel <i>Dented</i>	1	\$ 667.00 ✓
20.	Rear end panel garnish <i>could</i>	1	\$ 136.00 ✓
21.	Rear end panel garnish clip <i>new</i>	4	\$ 22.00 ✓
22.	Rear exhaust silencer box <i>Rep</i>	1	\$ 1050.00 +
23.	Rear exhaust silencer box heat shield <i>new</i>	1	\$ 149.00 +
24.	Rear spare tyre panel top board <i>new</i>	1	\$ 185.00 +
25.	Rear fender inner trim L/R <i>new</i>	2	\$ 840.00 +
Subtotal before discount			\$ 9257.40
Discount 10%			\$ 925.74
Subtotal 1			\$ 8331.66

4450.40

4005.36

S-N: 150

Local Rep
(ISO SN)

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

26 November 2020

QUOTATION FOR ACCIDENT REPAIR OF SLP2120Y VOLKSWAGEN POLO THIRD PARTY INSURER: CHINA TAIPING

<u>S/NETT Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1. Rear no plate <i>Del'd</i>	1	\$ 25 ✓
2. Rear no plate garnish <i>Del'd</i>	1	\$ 50 30
3. Rear windscreen sealant <i>new</i>	1	\$ 100 60
4. Rear reverse sensor <i>Del'd</i>	1	\$ 300 200
5. Rear bumper clip <i>new</i>	1	\$ 30 ✓
6. Vehicle body wrap (sticker) <i>new</i>	1	\$ 800 500
7. Rear fender inner trim clip <i>new</i>	2	\$ 60 x.
8. Rear end panel sealant <i>new</i>	1	\$ 50 ✓
S/Nett Total		\$ 1415

Rear Labour

To check wiring and rectify electrical faults where necessary	\$ 60 30
To apply anti-rush undercoat	\$ 150 60
To remove and refit rear fender inner trims and attachment to facilitate the repairs.	\$ 150 80
To remove and replace and reinstall rear reverse sensor	\$ 120 50
To remove and replace exhaust pipe	\$ 120 80
To transfer boot components parts to new boot	\$ 80 ✓
To remove and reinstall rear windscreen glass	\$ 120 ✓
To dismantle and replace body wrap for damage parts	\$ 400 200
To straighten, repair, realign on front affected area and replace damaged parts	\$ 1200 800
To spray painting on affected area	\$ 1200 800
Total Labour Cost	\$ 3520

Total Cost Of Repairs(Total cost of parts + Total labour cost)

\$ 13,266.66

LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer Signature: Date:

Admin Lj
4/5 26/11/22
07 Days
total: 7350.36
4/5: 581K