

# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,  
Harvest @ Woodlands Singapore 757322  
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJL 6610T  
Vehicle Model : HONDA FIT 1.3A  
Chassis Number : GE61143243

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID / <i>DD</i>	1	\$ 771.55 /
2	BOOT LID LOCK / <i>Jan</i>	1	\$ 189.55 /
3	BOOT LID INNER TRIM BOARD ? / <i>CRA</i>	1	\$ 150.25 /
4	BOOT LID INNER TRIM BOARD CLIPS ? / <i>Nec</i>	15	\$ 82.50 <i>30</i>
5	BOOT LID SCREEN INNER SEAL / <i>Nec</i>	1SET	\$ 108.90 /
6	BOOT LID WEATHERSTRIP / <i>Nec.</i>	1	\$ 92.35 /
7	BOOT LID ABSORBER LH & RH <i>X Svc</i>	2	\$ 320.48 <i>X</i>
8	"FIT" EMBLEM <i>X Svc</i>	1	\$ 35.10 <i>X</i>
9	"DAYTONA" STICKER / <i>Nec</i>	1	\$ 50.00 /
10	"H" LOGO / <i>Mis.</i>	1	\$ 30.20 /
11	REAR BUMPER / <i>Def.</i>	1	\$ 497.45 /
12	REAR BUMPER CLIPS / <i>Nec</i>	10	\$ 50.00 /
13	REAR BUMPER RETAINER LH & RH / <i>BR</i>	2	\$ 41.00 /
14	TAIL LAMP LH & RH ? / <i>CRA</i>	2	\$ 412.50 /
15	END PANEL ? / <i>DD.</i>	1	\$ 276.40 /
16	END PANEL UPPER GARNISH ? / <i>CRU</i>	1	\$ 120.85 /
17	END PANEL UPPER GARNISH CLIPS ? / <i>Nec</i>	10	\$ 55.00 <i>30</i>
18	REVERSE CAMERA <i>X Svc</i>	1	\$ 650.00 <i>X</i>
19) <i>Tuning cap - \$25.35 / Mis</i>			\$ 3934.08 <i>2,876.35</i>
Discount Less 20%			\$ 786.81 <i>- 20%</i>
List Prices Total			\$ 3,147.27 <i>2,301.08</i>

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR / <i>shot</i>	1SET	\$ 350.00 <i>200</i>
2	REAR NUMBER PLATE WITH HOLDER / <i>Def</i>	1SET	\$ 60.00 <i>35</i>
Special Nett Total			\$ 410.00 <i>235</i>
Spare Part's Total Price			\$ 3557.27

# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17  
 Harvest @ Woodlands Singapore 757322  
 Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJL 6610T  
 Vehicle Model : HONDA FIT 1.3A  
 Chassis Number : GE61143243

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Labour Descriptions	Charges
1 LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 1800.00 <i>800</i>
2 TO SPRAY PAINTING ON: BOOT LID (INNER & OUTER), REAR BUMPER, REAR END PANEL & BOOT FLOOR PANEL, REAR LHS & RHS FENDER.	\$ 1800.00 <i>600</i>
3 TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$ 150.00 <i>30</i>
4 TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO NEW BOOT LID & TEST FUNCTION	\$ 120.00 <i>60</i>
5 TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS	\$ 120.00 <i>X</i>
6 TO RESET & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS	\$ 280.00 <i>50</i>
7 TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 120.00 <i>30</i>
8 REMOVE & TRANSFER BOOT LID SCREEN TO NEW BOOT LID	\$ 150.00 <i>120</i>

Labour Total \$ 4540.00 *1,640*

Parts & Labour Total \$ 8097.27

*Repair dy - 4 days*

*LIS*

*After part photo*

*Sun Pin (L111)  
26/11/2020*

*TP with paper*

*2,301.08  
235  
1,690  
-----  
4,226.08  
-2090  
-----  
3,380.86*

*LIS  
\$3,400  
4 days*