

PAIR DETAILS

Reference: MRM-SG Version: 1.0 (Last Synchronised: 25 Nov 2020)

Part: 144 HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKE7907G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE <i>buc</i>			*950.60 FL
2	1		*TAILGATE GLASS <i>buc</i>	20.00	0.00	*630.50 FL
3	1		*TAILGATE GLASS MOULDING <i>ne</i>	20.00	0.00	*68.00 FL
4	1		*TAILGATE GLASS SEALANT <i>ne</i>	20.00	0.00	*40.00 FSS <i>u</i>
5	1		*TAILGATE GARNISH <i>? X su</i>	0	0.00	*130.60 FL <i>X</i>
6	1		*TAILGATE LOGO <i>ne</i>	20.00	0.00	*24.80 FL
7	1		*TAILGATE EMBLEM - JAZZ <i>ne</i>	20.00	0.00	*28.60 FL
8	1		*TAILGATE WIPER ARM <i>sc</i>	20.00	0.00	*43.70 FL
9	1		*TAILGATE WIPER ARM COVER <i>ca</i>	20.00	0.00	*13.60 FL
10	1		*TAILGATE WIPER MOTOR <i>? X su</i>	20.00	0.00	*332.40 FL <i>X</i>
11	1		*TAILGATE LOCK <i>am</i>	20.00	0.00	*211.90 FL
12	1		*TAILGATE WEATHERSTRIP <i>ne</i>	20.00	0.00	*92.30 FL
13	1		*TAILGATE INNER TRIM <i>? X su</i>	20.00	0.00	*255.40 FL <i>X</i>
14	1		*TAILGATE PULL POCKET <i>? X su</i>	20.00	0.00	*24.60 FL <i>X</i>
15	1		*TAILGATE LOCK STRICKER <i>X su</i>	20.00	0.00	*41.90 FL <i>X</i>
16	2		*TAILGATE ASSY RH & LH <i>PH/LH - RSC. CR</i>	20.00	0.00	*516.80 FL
17	1		*TAILLAMP PANEL LH <i>? X su</i>	20.00	0.00	*156.90 FL <i>X</i>
18	2		*TAILLAMP CLIPS <i>ne</i>	20.00	0.00	*11.00 FL
19	1		*TAILLAMP LOWER BRACKET LH <i>? X su</i>	20.00	0.00	*58.40 FL <i>X</i>
20	1		*REAR FENDER LH <i>buc</i>	20.00	0.00	*714.20 FL
21	2		*REAR FENDER INNER TRIM RH & LH <i>2de</i>	20.00	0.00	*524.40 FL
22	1		*REAR END PANEL <i>buc</i>	20.00	0.00	*364.50 FL
23	1		*REAR END PANEL INNER TRIM <i>photo</i>	20.00	0.00	*70.80 FL
24	1		*SPARE WHEEL PANEL (REPAIR) <i>R</i>	20.00	0.00	-
25	1		*SPARE TYRE BOARD <i>2de</i>	20.00	0.00	*207.10 FL
26	1		*REAR TOW COVER <i>X su</i>	20.00	0.00	*21.80 FL <i>X</i>
27	1		*REAR BUMPER <i>de</i>	20.00	0.00	*894.80 FL
28	1		*REAR BUMPER LOWER GARNISH <i>de</i>	20.00	0.00	*103.40 FL
29	1		*REAR BUMPER RETAINER LH <i>ne</i>	20.00	0.00	*18.50 FL
30	10		*REAR BUMPER CLIPS <i>ne</i>	20.00	0.00	*30.00 FL
31	1		*REVERSE SENSOR (SET) <i>ne</i>	0	0.00	*200.00 FS <i>u</i>
32	1		*REAR QUARTER GLASS SEALANT <i>ne</i>	0	0.00	*40.00 FS <i>u</i>
33	1		*REAR VIEW CAMERA <i>X su</i>	0	0.00	*350.00 FS <i>X</i>
34	1		*REAR FENDER COWLING LH <i>? X su</i>	20.00	0.00	*85.10 FL <i>X</i>
35	1		*REAR NUMBER PLATE <i>X su</i>	0	0.00	*40.00 FS <i>X</i>
Sub Total (\$\$)						7,296.60
- List Item Discount on L Items (\$\$)						1,325.32
Total Parts (\$\$)						5,971.28

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Supplemental: 1PC REAR CHASSIS MEMBER LH 658.40 / Repair

TO CHECK CHASSIS ALIGNMENT ON LASER LOCK MECHANISM - 300.00 ~~150~~
250 / (-labour)

Estimates on Miscellaneous Items

Particulars	Amount
Miscellaneous Items	11.00
OD/TP Case (Insurer)	11.00
Sub Total (\$\$)	11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUT/WELD REAR FENDER LH, REAR END PANEL, KNOCK AND STRAIGHTEN REAR BODY MEMBER, SPARE WHEEL PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	1000 1200.00
2	SPRAY PAINT TAILGATE, REAR FENDER LH, TAILLAMP PANELS, REAR END PANEL, SPARE WHEEL PANEL, REAR BUMPER, REAR BODY MEMBER	New	900 1000.00
3	REMOVE & REINSTALL TAILGATE GLASS AND CHECK WATER LEAKAGE	New	120.00 100.00
4	REMOVE & REFIT TAILGATE INNER TRIM, MECHANISM AND CHECK LOCKING SYSTEM	New	60.00 80.00
5	REMOVE & REFIT PETROL TANK, PIPE, HOSE	New	80.00 60.00
6	REMOVE & REINSTALL REVERSE SENSOR AND CHECK FUNCTION	New	50.00 80.00
7	REMOVE & REFIT REAR SEAT ASSY, UPHOLSTERY, INNER TRIM, COVERING	New	150.00 80.00
8	RUST PROOF AFFECTED AREA	New	100.00 60.00
Gross Labour Cost (\$\$)			2,760.00

Report was unsubmitted during this print-out.
Generated using Morimen e-Claims IEAS
< END OF ESTIMATES >

4415.60
280.00
11.00
2530.00
7236.60
20%
5789.28

43-5750.00
11 days

Rasul
Hp 90010068
11 days
43

26/11/2020 @ 1425

Resing after repair