



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013060/Utd3q2	
			Date: 05/01/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 7992B	Veh. Inspected	SVJ 6551C	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2003445/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	GE61212003	Colour	BLACK	
Odometer	123766 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	DUNLOP	6 mm	
L/H Front Tyre	185/55 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/55 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/55 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2020	Inspection Date	26/11/2020	
Survey held at	8 KAKI BUKIT AVE 4 # 01-49 PREMIER			
Repairer	1ST AUTO PRO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	