

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06289

Vehicle Insured : SHA9439J

Accident Date : 24-Nov-2020

Date : 25-Nov-2020

Our Ref : 020168 (FIRST) / CHAN

PAGE : 1

SINGAPORE RED CROSS SOCIETY
15 PENANG LANE
SINGAPORE RED CROSS
Singapore 238486

Not Authorized
11 Pys @ 28501
Returning After Pains

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE 3.0 HIGH ROOF PC5128C

1 pc Tail gate
1 pc Tail gate outer garnish
1 pc Tail gate inner lock
1 pc Rear bumper fascia
4 pcs Rear bumper clip
1 pc Rear end panel -outer
1 pc Rear end panel -inner

Bu 2,162.10 —
Sn 119.20 X
K 249.60 X
Bu 354.60 —
@ S\$ 4.10 *Sn* 16.40 —
Bu 371.30 *K*
K 1,143.70 *K*

4,416.90
Less 25% : 1,104.22

1 pc Rear bumper reverse sensor(4pc
1 pc Rear w/s glass sealant
1 pc Tail gate 60km/h sticker
1 pc Tail gate lettering

CM 3,312.68 *3000*
Sn 400.00 *sn*
Sn 40.00 *sn*
Sn 15.00 *sn*
Sn 240.00 *sn*

To remove & refix rear windscreen
glass and conduct water leak test.

1201
150.00

To apply undersealing

Sn 30.00 *71*

To putty and spray replaced parts

400.00 *360*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *300*

Total : S\$ 5,007.68

Singapore Dollars Five Thousand and Seven
Cents Sixty Eight Only

LKK Auto Consultants hence notify
and repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: