



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2100392

INV Date 18/01/2021

Reference CC4/LPC20013087/R1pa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 239Y

Insured Veh. YN 8921U

Claim No. 20/20/20/VC05/023943

Policy No. Z20VC05005862

Accident Date 25/11/2020

Inspection Date 26/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20013087/R1pa3q2 Date: 18/01/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8921U	Veh. Inspected	GBK 239Y	
Policy No.	Z20VC05005862	Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023943	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	26/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	SSANGYONG ACTYON SP 2.2D	c.c	2157	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KPADA1EESJP329637	Colour	GREY	
Odometer	18529 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/75 R16	KUMHO	7 mm	
L/H Front Tyre	225/75 R16	KUMHO	7 mm	
R/H Rear Tyre	225/75 R16	KUMHO	7 mm	
L/H Rear Tyre	225/75 R16	KUMHO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/11/2020	Inspection Date	26/11/2020	
Survey held at	MOTORWAY CAR CARE CENTRE PTE LTD 1094 LOWER DELTA ROAD MOTORWAY BUILDING . SINGAPORE 169205			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 239Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,600.00	1,250.00
1	REAR BUMPER RETAINER RH	SERVICEABLE	89.00	-
1	REAR BUMPER REFLECTOR LENS RH	SERVICEABLE	68.00	-
1	SSANGYONG EMBLEM	NECESSARY	89.00	65.00
1	ACTYON SPORT EMBLEM	NECESSARY	89.00	65.00
1	SSANGYONG LOGO	NECESSARY	190.00	95.00
1	REAR TAILLAMP RH	BROKEN	780.00	515.00
1	REAR BOOTLID	BENT	2,200.00	1,950.00
1	REAR BOOT OUTER CHROME MOULDING	SCRATCHED	290.00	290.00
1	REAR BOOT LATCH ASSY RH	BENT	120.00	120.00
1	REAR BOOT INNER TRIM	SERVICEABLE	350.00	-
1	DECK SIDE RH	TO REPAIR SEE LABOUR	2,800.00	-
	LESS 10% DISCOUNT		-866.50	-435.00
			7,798.50	3,915.00
1	70KM/H STICKER (SN)	NECESSARY	45.00	10.00
	LESS 10% DISCOUNT		-4.50	-
			40.50	10.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
1	SET REVERSE SENSORS (SN)	SCRATCHED	380.00	220.00
			420.00	260.00
	<u>LABOUR</u>			
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT ,CUT/WELD ,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF DECK SIDE RH .		2,800.00	1,200.00
	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS.		2,250.00	1,350.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK REAR WIRES ,CONNECTORS ,REPLACE DAMAGED LAMPS REVERSE SENSORS.		180.00	80.00
	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	60.00
	TO CARRY OUT DIAGNOSTIC TEST.		400.00	250.00
			5,810.00	2,940.00
GRAND TOTAL			14,069.00	7,125.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CC4/LPC20013087/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 239Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 239Y

RE-INSPECTION

