

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013088/R1BA3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHA811B	Insured Vehicle No :	SHC2272H
Date of Loss:	25/11/2020	Nature of Claim:	TP
		Claim No:	MCT20110404

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA811B		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU662613
Reg. Date:	13/08/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU077048
Colour:	Yellow	Odometer:	610861 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,742.69	5,427.79	2,314.90	29.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	2,220.00	2,150.00	49.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,112.69	7,647.79	4,464.90	36.86
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	12,112.69	6,100.00	6,012.69	49.64
+ GST 7.00/7.00% (S\$)	847.89	427.00	420.89	49.64
Nett Amount (S\$)	12,960.58	6,527.00	6,433.58	49.64
+ Loss of Use (6.0 x S\$40.00/day) (S\$)		240.00		
+ Car Rental (6.0 x S\$103.43/day) (S\$)		620.58		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,395.03		
Global Sum Settlement (S\$)		7,350.00		

INSPECTION

Date of Assignment:	26/11/2020		
Date Inspected:	26/11/2020	Inspected At:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825

3/30/2021

Adjuster Report

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Mar 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA811B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FRONT BUMPER	Deformed	599.68 FL	*599.68 FL
3	1		*FRONT BUMPER RETAINER RH	Cracked	48.32 FL	*48.32 FL
4	1		*HEADLAMP RH	Scratched	1,808.10 FL	*1,808.10 FL
5	1		*FRONT SUPPORT PANEL	Cracked	962.87 FL	*962.87 FL
6	1		*FRONT FENDER RH	Buckled	659.50 FL	*659.50 FL
7	1		*FRONT FENDER INNER BRACKET RH	Serviceable	55.12 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD RH	Missing	185.12 FL	*185.12 FL
9	1		*FRONT WHEEL CAP RH	Deformed	265.50 FL	*265.50 FL
10	1		*FRONT WHEEL RIM RH	Serviceable	255.33 FL	*- FL
11	1		*FRONT ABSORBER RH	Serviceable	342.20 FL	*- FL
12	1		*FRONT LOWER ARM RH	Serviceable	529.30 FL	*- FL
13	1		*FRONT TIE ROD END RH	Serviceable	114.97 FL	*- FL
14	1		*SIDE MIRROR RH	Cracked	518.40 FL	*518.40 FL
15	1		*REAR WHEEL CAP RH	Scratched	265.50 FL	*265.50 FL
16	1		*FRONT FENDER INNER SHIELD LH	Serviceable	185.12 FL	*- FL
17	1		*FRONT WHEEL CAP LH	Scratched	265.50 FL	*265.50 FL
18	1		*FRONT WHEEL RIM LH	Serviceable	255.33 FL	*- FL
19	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
21	1		*FRONT FENDER ADS STICKER RH	Necessary	150.00 FS	*100.00 FS
22	1		*FRONT FENDER INNER SHIELD CLIP SET RH	Necessary	35.00 FS	*35.00 FS
23	1		*FRONT TYRE RH (70%)	Cut	300.00 FS	*210.00 FS
24	1		*REPAIR FRONT WINDSCREEN PILLAR RH (NPA)	Repair	0.00 FS	*- FS
25	1		*REPAIR FRONT DOOR RH (NPA)	Not Necessary	0.00 FS	*- FS
26	1		*FRONT DOOR STICKER -COMFORT DELGRO RH	Not Necessary	150.00 FS	*- FS
27	1		*FRONT DOOR ADS STICKER RH	Not Necessary	180.00 FS	*- FS
28	1		*REPAIR REAR DOOR RH (NPA)	Repair	0.00 FS	*- FS
29	1		*REAR DOOR STICKER -COMFORT DELGRO LOGO RH }	Necessary	120.00 FS	*120.00 FS
30	1		*REAR DOOR STICKER -APP STORE & BOOK NOW RH }	Necessary	100.00 FS	*- FS
31	1		*REAR DOOR ADS STICKER RH	Necessary	180.00 FS	*100.00 FS
32	1		*REPAIR REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
33	1		*REAR FENDER ADS STICKER RH	Necessary	180.00 FS	*100.00 FS
34	1		*REPAIR REAR BUMPER (NPA)	Not Necessary	0.00 FS	*- FS
35	1		*FRONT FENDER INNER SHIELD CLIP SET LH	Not Necessary	35.00 FS	*- FS
36	1		*FRONT TYRE LH (70%)	Cut	300.00 FS	*210.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,205.86	6,543.49
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,463.17	1,115.70
Total Parts (\$\$)	7,742.69	5,427.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREA	New	1,200.00	900.00
2	RUST PROOFING	New	120.00	40.00
3	DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	New	180.00	0.00
4	ADJUST HEADLAMP AIM	New	80.00	30.00
5	R&R RADIATOR & CONDENSER & TURBO INTERCOOLER	New	180.00	80.00
6	VACUUM & TOP UP AIR COND GAS R-134A	New	150.00	60.00
7	R&R FRONT UNDERCARRIAGE	New	250.00	0.00
8	R&R FRONT RIM & TYRE LH }	New	80.00	60.00
9	R&R FRONT RIM & TYRE RH }	New	80.00	0.00
10	CONDUCT 4 WHEEL ALIGNMENT & BALANCING	New	150.00	80.00
11	RESPRAY FRONT BUMPER	New	250.00	200.00
12	RESPRAY FRONT FENDER RH	New	250.00	200.00
13	RESPRAY FRONT WINDSCREEN PILLAR RH	New	250.00	100.00
14	RESPRAY SIDE MIRROR RH	New	150.00	70.00
15	RESPRAY FRONT DOOR RH	New	250.00	0.00
16	RESPRAY REAR DOOR RH	New	250.00	200.00
17	RESPRAY REAR FENDER RH	New	250.00	200.00
18	RESPRAY REAR BUMPER	New	250.00	0.00
Gross Labour Cost (S\$)			4,370.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >