5/17/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/LCR17023109/K1EA3Q2-1

Date:

17/05/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

0999995008 SLJ3995P

Claimant Vehicle No:

SHA3904Y 03/12/2017 Insured Vehicle No:

Nature of Claim:

TP

Claim No:

6575447979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA3904Y**

Make & Model: HYUNDAI 140, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4FDFU537806 Chassis No: KMHLB41UMFU065864

Reg. Date: 24/03/2015 (Man. Year: 2014)

Odometer:

371791 km

Colour: Blue

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Handbrake (Serviceable):

Engine Modification: Yes

No

Yes

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size:

205/60 R16

Front Left Side:

West Lake 7 mm

Rear Left Side: West Lake 7 mm

West Lake 7 mm

Front Right Side:

West Lake 7 mm

Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	0.00	0.00	0.00	
	Approved Total (Overridden) (S\$)		10,176.23		

Nett Amount (S\$)	0.00	10,176.23	-10,176.23
+ Loss of Use (28.0 x S\$50.00/day) (S\$)		1,400.00	
+ Car Rental (28.0 x S	\$129.28/day) (S\$)	3,619.84	
Nett Liability (S\$)		15,196.07	
Global Sum Settlement (S\$)		15,000.00	

INSPECTION

Date of Assignment: 05/12/2017

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 05/12/2017 Inspected At:

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 0.0 days

KALVIN ANG WEI KUN Adjuster: Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

BOOK VALUE : \$64,393.29

LTA REIMBURSEMENT VALUE (RV) : \$43,447.00

NETT VALUE : \$20,946.29

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >