

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0906/2020/NS
DATE : 24-Nov-20
WIP : 58697

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

10 days exclude 2 Sundays

jb 5 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR POLLINA STEFANO
ADDRESS : 10 TANGLIN WALK
SINGAPORE 547880
TELEPHONE : HP +65 91180113
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900259405
VEHICLE NO : **SMR 1135 P**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 19/12/2019
ENGINE NO : DAX 058077
CHASSIS NO : WAUZZZF7Y7K2123300
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Nov-20
PLACE OF ACCIDENT : ALEXANDRA ROAD/TRAFFIC LIGHT WITH
DEPOT ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 1135 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N	\$ 800.00	\$	500.00
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS.	S/N	\$ 800.00	\$	560.00
4	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 280.00		
TOTAL LABOUR CHARGES		:	\$ 2,360.00	\$	1,540.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 1135 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>	\$	1,540.00
5	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 \$	1,400.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET, RHS FRONT DOOR AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>(Q5 Added 3 days for lock carrier)</i>	\$ 7,200.00 \$	3,000.00
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, BOTH FRONT FENDERS, BOTH FRONT WHEEL ARCH TRIMS, BOTH FRONT DOORS AND BOTH FRONT UPPER A-PILLARS.	\$ 9,000.00 \$	4,800.00
8	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00 \$	192.00
TOTAL LABOUR CHARGES		: \$ 17,984.00 \$	10,932.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER		\$	2,595.00	\$ 2,075.60
2	FRONT BUMPER FIXING PARTS		\$	267.00	
3	FRONT BUMPER SECURING STRIP - LH/RH	2	\$	74.00	
4	FRONT BUMPER CLOSING ELEMENT - LH/RH	2	\$	222.00	
5	FRONT BUMPER GRILLE - CENTRE		\$	142.00	
6	FRONT SPOILER		\$	754.00	
7	FRONT BUMPER UNDERRUN BAR		\$	474.00	
8	FRONT BUMPER CLOSING ELEMENT		\$	171.00	
9	RADIATOR GRILLE		\$	3,490.00	\$ 2,792.00
10	QUATTRO INSCRIPTION		\$	95.00	\$ 75.36
11	RADIATOR GRILLE STRIKER PLATE		\$	241.00	\$ 192.80
12	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2	\$	1,148.00	\$ 458.80
13	FRONT BUMPER END CAP - LH/RH	2	\$	182.00	
14	LOCKING CLIP	4	\$	15.00	
15	FRONT BUMPER CARRIER		\$	911.00	
16	FRONT BUMPER FOAM FILLER PIECE		\$	285.00	\$ 228.00
17	FRONT BUMPER TOP COVER		\$	127.00	
18	FRONT BUMPER GUIDE SECTION - LH/RH	2	\$	76.00	\$ 30.16
19	FRONT BUMPER BRACKET - LH/RH	2	\$	508.00	
20	CAUTION SIGN STICKER	NEC	\$	14.00	
SUB TOTAL SPARE PARTS		:	\$	11,791.00	\$ 5,852.72

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
	<i>c/f</i>			\$	5,852.72
21	AIRCON STICKER	NEC	\$ 20.00		
22	HORN - LH LOW TONE		\$ 193.00		
23	HORN - RH HIGH TONE		\$ 193.00		
24	FRONT PARKING AID SENSOR - INNER	2	\$ 484.00		
25	FRONT PARKING AID SEAL RING	4	\$ 14.00		
26	FRONT BUMPER WIRING SET		\$ 405.00		
27	FRONT FENDER - LH/RH	2	\$ 2,822.00	\$	1,128.80
28	FRONT FENDER BRACKET - LH/RH	2	\$ 34.00		
29	FRONT FENDER BRACE - LH/RH	2	\$ 444.00	\$	355.20
30	FRONT FENDER ATTACHMENT PARTS	2	\$ 131.00		
31	WHEEL HOUSING LINER - LH/RH	2	\$ 550.00		
32	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 38.00		
33	WHEEL SPOILER - LH		\$ 159.00		
34	WHEEL SPOILER - RH		\$ 153.00		
35	BONNET		\$ 4,012.00	\$	3,209.60
36	BONNET LID HINGE - LH/RH	2	\$ 318.00		
37	BONNET ATTACHMENT PARTS		\$ 139.00		
38	BONNET IMPACT PROTECTION - CENTRE		\$ 27.00	\$	21.52
39	BONNET IMPACT PROTECTION - LH		\$ 28.00	\$	21.84
40	BONNET IMPACT PROTECTION - RH		\$ 27.00	\$	21.52
SUB TOTAL SPARE PARTS		:	\$ 10,191.00	\$	10,611.20



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
		<i>c/f</i>		\$	10,611.20
41	BONNET SOUND ABSORBER		\$ 314.00		
42	PLENUM CHAMBER COVER		\$ 143.00		
43	BONNET STRIKER - LH/RH	2	\$ 238.00		
44	BONNET LID LOCK	2	\$ 423.00		
45	FLAT CONNECTOR HOUSING	2	\$ 25.00		
46	BONNET BOWDEN CABLE - CENTRE		\$ 57.00		
47	BONNET RELEASE ELEMENT		\$ 57.00		
48	BONNET RELEASE LEVER		\$ 14.00		
49	S-LINE INSCRIPTION	2	\$ 244.00	\$	195.20
50	HEADLIGHT MOUNTING - LH/RH	2	\$ 234.00	\$	187.20
51	LOCK CARRIER BRACE - LH/RH LOWER	2	\$ 112.00		
52	LED HEADLIGHT - LH/RH	2	\$ 15,862.00	\$	12,689.60
53	LIFT CYLINDER - LH/RH	2	\$ 276.00		
54	LIFT CYLINDER HOSE		\$ 124.00		
55	FRONT WHEEL COVER - LH/RH	2	\$ 1,250.00	\$	1,000.00
56	LOCK CARRIER		\$ 1,384.00	\$	1,107.20
57	LOCK CARRIER SUPPORT - LH/RH	2	\$ 106.00		
58	TEMPERATURE SENSOR BRACKET		\$ 16.00		
59	READY MIX COOLANT		\$ 177.00	\$	141.44
60	RADIATOR AIR GUIDE - UPPER		\$ 48.00		
SUB TOTAL SPARE PARTS		:	\$ 21,104.00	\$	25,931.84

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & S/NETT	PRICES	REMARKS
		<i>c/f</i>		\$	25,931.84
61	RADIATOR AIR GUIDE - CENTRE		\$ 42.00		
62	RADIATOR AIR GUIDE - LOWER		\$ 48.00		
63	RADIATOR AIR GUIDE - LH/RH	2	\$ 116.00	\$	91.52
64	RADIATOR LOUVRE		\$ 528.00		
65	SERVOMOTOR		\$ 174.00		
66	FRONT DOOR - RH		\$ 3,118.00		
67	FRONT DOOR OUTER SEAL - RH	NEC	\$ 203.00		
68	BONDING AGENT	NEC	\$ 47.00		
69	CLEANING SOLUTION	NEC	\$ 65.00		
70	FRONT DOOR CATCH		\$ 144.00		
71	WATER DEFLECTOR STRIP - LH/RH	2	\$ 132.00		
72	WINDOW SLOT SEAL - LH/RH FRONT	2	\$ 1,218.00	\$	973.60
73	WINDOW GUIDE TRIM STRIP - LH/RH	2	\$ 674.00		
74	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
75	SUPPLEMENTARY		\$ 29.00	\$	24.40
76	SUNDRIES		\$ 400.00		
TOTAL SPARE PARTS		:	\$ 50,084.00	\$	27,081.36
TOTAL LABOUR CHARGES		:	\$ 17,984.00	\$	10,932.00
GRAND TOTAL		:	\$ 68,068.00	\$	38,013.36

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-13/01/21



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0906/2020/NS
12-Dec-20
GROGE WONG
1 OF 1
SMR 1135 P
AUDI Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	FRONT FENDER TOP SUPPORT OUTER COVER - RH	\$ 29.00	\$ 24.40
TOTAL		\$ 29.00	\$ 24.40

For Premium Automobiles Pte Ltd

Authorised Signature