

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0906/2020/NS
DATE : 24-Nov-20
WIP : 58697

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR POLLINA STEFANO
ADDRESS : 10 TANGLIN WALK
SINGAPORE 547880
TELEPHONE : HP +65 91180113
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900259405
VEHICLE NO : **SMR 1135 P**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 19/12/2019
ENGINE NO : DAX 058077
CHASSIS NO : WAUZZZF7K2123300
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Nov-20
PLACE OF ACCIDENT : ALEXANDRA ROAD/TRAFFIC LIGHT WITH
DEPOT ROAD



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 1135 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00 280 500 <i>865</i>	
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS.	S/N \$ 800.00 280 560	
4	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00 X	
TOTAL LABOUR CHARGES		: \$ <u>2,360.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 1135 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	1400 fls.
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET, RHS FRONT DOOR AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00	1500 3000 fls.
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, BOTH FRONT FENDERS, BOTH FRONT WHEEL ARCH TRIMS, BOTH FRONT DOORS AND BOTH FRONT UPPER A-PILLARS.	\$ 9,000.00	4800 8 x 550 = 4400 AFC Trim x 2 = 200 x 2 = 400 4800
8	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		: \$ 17,984.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Disl'd</i>		\$ 2,595.00	✓ 2075.60
2 FRONT BUMPER FIXING PARTS <i>new</i>		\$ 267.00	x
3 FRONT BUMPER SECURING STRIP - LH/RH <i>Not new</i>	2	\$ 74.00	x
4 FRONT BUMPER CLOSING ELEMENT - LH/RH <i>Not new</i>	2	\$ 222.00	x
5 FRONT BUMPER GRILLE - CENTRE <i>new</i>		\$ 142.00	x
6 FRONT SPOILER <i>new</i>		\$ 754.00	x
7 FRONT BUMPER UNDERRUN BAR <i>new</i>		\$ 474.00	x
8 FRONT BUMPER CLOSING ELEMENT <i>new</i>		\$ 171.00	x
9 RADIATOR GRILLE <i>new</i>		\$ 3,490.00	✓ 2792.00
10 QUATTRO INSCRIPTION <i>new</i>		\$ 95.00	✓ 75.36
11 RADIATOR GRILLE STRIKER PLATE <i>new</i>		\$ 241.00	✓ 192.80
12 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>Not new</i>	2	\$ 1,148.00	574. 458.80
13 FRONT BUMPER END CAP - LH/RH <i>new</i>	2	\$ 182.00	x
14 LOCKING CLIP <i>new</i>	4	\$ 15.00	x
15 FRONT BUMPER CARRIER <i>Not new</i>		\$ 911.00	x
16 FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>		\$ 285.00	✓ 228.00
17 FRONT BUMPER TOP COVER <i>Not new</i>		\$ 127.00	x
18 FRONT BUMPER GUIDE SECTION - LH/RH <i>Not new</i>	2	\$ 76.00	x ✓ 30.16
19 FRONT BUMPER BRACKET - LH/RH <i>Not new</i>	2	\$ 508.00	x
20 CAUTION SIGN STICKER <i>Not new</i>	NEC	\$ 14.00	x
SUB TOTAL SPARE PARTS	:	\$ 11,791.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 AIRCON STICKER <i>Not in</i>	NEC	\$	20.00	X
22 HORN - LH LOW TONE <i>Not in</i>		\$	193.00	+
23 HORN - RH HIGH TONE		\$	193.00	+
24 FRONT PARKING AID SENSOR - INNER <i>Not in</i>	2	\$	484.00	X
25 FRONT PARKING AID SEAL RING <i>Not in</i>	4	\$	14.00	24 X
26 FRONT BUMPER WIRING SET <i>Not in</i>		\$	405.00	X
27 FRONT FENDER - LH/RH <i>RH Buckled</i>	2	\$	2,822.00	1411 1128.80
28 FRONT FENDER BRACKET - LH/RH <i>Not in</i>	2	\$	34.00	X
29 FRONT FENDER BRACE - LH/RH <i>Dented.</i>	2	\$	444.00	✓ 355.20
30 FRONT FENDER ATTACHMENT PARTS <i>Not in</i>	2	\$	131.00	+
31 WHEEL HOUSING LINER - LH/RH <i>Not in</i>	2	\$	550.00	+
32 WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not in</i>		\$	38.00	+
33 WHEEL SPOILER - LH <i>Not in</i>		\$	159.00	+
34 WHEEL SPOILER - RH		\$	153.00	+
35 BONNET <i>Dented</i>		\$	4,012.00	✓ 3209.60
36 BONNET LID HINGE - LH/RH <i>Not in</i>	2	\$	318.00	+
37 BONNET ATTACHMENT PARTS <i>Not in</i>		\$	139.00	+
38 BONNET IMPACT PROTECTION - CENTRE <i>Not in</i>		\$	27.00	✓ 21.52
39 BONNET IMPACT PROTECTION - LH <i>Not in</i>		\$	28.00	✓ 21.84
40 BONNET IMPACT PROTECTION - RH <i>Not in</i>		\$	27.00	✓ 21.52
SUB TOTAL SPARE PARTS	:	\$	10,191.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 BONNET SOUND ABSORBER <i>Not on</i>		\$ 314.00	+
42 PLENUM CHAMBER COVER		\$ 143.00	+
43 BONNET STRIKER - LH/RH	2	\$ 238.00	+
44 BONNET LID LOCK <i>Not on</i>	2	\$ 423.00	+
45 FLAT CONNECTOR HOUSING	2	\$ 25.00	+
46 BONNET BOWDEN CABLE - CENTRE		\$ 57.00	+
47 BONNET RELEASE ELEMENT		\$ 57.00	+
48 BONNET RELEASE LEVER		\$ 14.00	+
49 S-LINE INSCRIPTION <i>Not on</i>	2	\$ 244.00	✓ 195.20
50 HEADLIGHT MOUNTING - LH/RH <i>cracked.</i>	2	\$ 234.00	✓ 187.20
51 LOCK CARRIER BRACE - LH/RH LOWER <i>Not on</i>	2	\$ 112.00	X
52 LED HEADLIGHT - LH/RH <i>Not on</i>	2	\$ 15,862.00	✓ 7931 12,689.60
53 LIFT CYLINDER - LH/RH	2	\$ 276.00	+
54 LIFT CYLINDER HOSE <i>Not on</i>		\$ 124.00	+
55 FRONT WHEEL COVER - LH/RH <i>Not on</i>	2	\$ 1,250.00	✓ 1000
56 LOCK CARRIER <i>Not on Cracked.</i>		\$ 1,384.00	✓ 1107.20
57 LOCK CARRIER SUPPORT - LH/RH <i>Not on</i>	2	\$ 106.00	X
58 TEMPERATURE SENSOR BRACKET <i>Not on</i>		\$ 16.00	X
59 READY MIX COOLANT <i>Not on</i>		\$ 177.00	✓ 141.44
60 RADIATOR AIR GUIDE - UPPER <i>Not on</i>		\$ 48.00	X
SUB TOTAL SPARE PARTS	:	\$ 21,104.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1135 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
61 RADIATOR AIR GUIDE - CENTRE <i>the new</i>		\$ 42.00	X
62 RADIATOR AIR GUIDE - LOWER <i>the new</i>		\$ 48.00	X
63 RADIATOR AIR GUIDE - LH/RH <i>Deformed.</i>	2	\$ 116.00	✓ 91.52
64 RADIATOR LOUVRE <i>the new</i>		\$ 528.00	+
65 SERVOMOTOR <i>the new</i>		\$ 174.00	+
66 FRONT DOOR - RH <i>Regis</i>		\$ 3,118.00	+
67 FRONT DOOR OUTER SEAL - RH <i>the new</i>	NEC	\$ 203.00	+
68 BONDING AGENT	NEC	\$ 47.00	+
69 CLEANING SOLUTION <i>the new</i>	NEC	\$ 65.00	+
70 FRONT DOOR CATCH		\$ 144.00	+
71 WATER DEFLECTOR STRIP - LH/RH <i>the new</i>	2	\$ 132.00	66. X
72 WINDOW SLOT SEAL - LH/RH FRONT <i>the new</i>	2	\$ 1,218.00	✓ 973.60
73 WINDOW GUIDE TRIM STRIP - LH/RH <i>the new</i>	2	\$ 674.00	+
74 FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60.00
75 SUNDRIES <i>the new</i>		\$ 400.00	X
TOTAL SPARE PARTS	:	\$ 50,055.00	
TOTAL LABOUR CHARGES	:	\$ 17,984.00	
GRAND TOTAL	:	\$ 68,039.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *26/11/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 10 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Shirley,

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0906/2020/NS
12-Dec-20
GROGE WONG
1 OF 1
SMR 1135 P
AUDI Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	FRONT FENDER TOP SUPPORT OUTER COVER - RH <i>nlcc</i>	\$ 29.00	<i>✓ 34.00</i>
TOTAL		\$ 29.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian L
14/12/20
sls.