

ASS. REC. BY:

TGLM

REF:

CC4/A1420013105/B^e93

gasper

ASSIGNMENT

From:

Date: 27/11/2020

Veh No:

SGP 9828C

Yr Regn: 29/11/2016

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SGP 9828C

Make:

Mercedes E200

C.C. 1991

at Workshop m/s

Dean Autopro

Colour:

Silver

A/C: Insured / Std / NI / NA

of

160 Sin Hung Dr, # 07-14

Sp. Reading

41 483

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

27492030771658

Policy No.

C/No:

WDD2130422A076326

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or


(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its
repair at the time of inspection.

Tyre Size:

F: 255/40/19

R: 255/40/19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

130,000

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

5

days

Res.: Yes or No

D.O.A.

26/11/2020

D.O.I.

27/11/2020

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Dean Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COR recommended L/S 4550/2

TGLM

4/12/2020

MV 130,000/2

PV 80,203/1

NV 49,797/2

TGLM

28/11/2020

Date/Time, File Pass to?



: Preli. Report

Days Of Repair:

1)



: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:



: Site Insp (\$

S + RS, SI



: Interview (\$

Photos



: Tech. Invs (\$

Others



: Weekend (\$

TOTAL

Rep. Format:

Lump Sum / L/S / C

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SGP 9828 C**
 Model : **MERCEDES E200**
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	BOOTLID	1	\$ 2,399.00	\$ 2,399.00
2	BOOTLID LOGO	1	\$ 145.00	\$ 90.00 145.00
3	BOOTLID EMBLEM 'E200'	1	\$ 94.21	\$ 82.00 94.21
4	BOOTLID EMBLEM 'C&C'	1	\$ 68.00	\$ 45.00 68.00
5	BOOTLID EMBLEM '9G TRONIC'	1	\$ 94.21	\$ 65.00 94.21
6	BOOTLID OUTER CHROME MOULDING	1	\$ 168.00	\$ ✓ 168.00
7	BOOTLID INNER LOCK	1	\$ 483.60	\$ 483.60
8	BOOTLID WEATHER STRIP	1	\$ 295.60	\$ 295.60
9	BOOTLID INNER TRIM BOARD	1	\$ 983.60	\$ 983.60
10	BOOTLID NUMBER PLATE LAMP	2	\$ 88.23	\$ 176.46
11	REAR BUMPER	1	\$ 2,044.00	\$ 1,590.00 2,044.00
12	REAR BUMPER RETAINER	2	\$ 65.00 137.86	\$ 130.00 275.72
13	REAR BUMPER DIFFUSER	1	\$ 583.36	\$ 300.00 583.36
14	REAR BUMPER DIFFUSER OUTER CHROME	1	\$ 168.00	\$ ✓ 168.00
15	REAR BUMPER REFLECTOR	2	\$ 68.34	\$ 136.68
16	REAR BUMPER REINFORCEMENT	1	\$ 751.33	\$ 751.33
17	REAR BUMPER BRACKET	1	\$ 101.82	\$ 101.82
18	REVERSE SENSOR <i>i-MIS</i>	<i>1 SC</i>	\$ 180.00 245.00	\$ 360.00 1,470.00
19	REAR END PANEL	1	\$ 1,752.30	\$ 1,752.30
20	REAR END PANEL TOP GARNISH	1	\$ 347.74	\$ 347.74
21	REAR FENDER LH	1	\$ 2,325.00	\$ 2,325.00
22	REAR FENDER INNER TRIM BOARD LH	1	\$ 325.00	\$ 325.00
23	REAR WINDSCREEN MOULDING	1	\$ 254.00	\$ 254.00
24	REAR EXHAUST CHROME MOULDING	<i>1</i>	\$ 158.00	\$ 80.00 316.00
25	TAIL LAMP	2	\$ 596.00 894.00	\$ 1138.00 1,788.00
26	TAIL LAMP LOWER BRACKET	2	\$ 185.00	\$ 370.00
Parts Sub Total :				\$ 17,916.63
10% DISCOUNT				\$ 1,791.66
PARTS TOTAL :				\$ 16,124.97

4350.68

@ 10%

435.07

3915.61

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	SUNDRIES	1	\$ 80.00	\$ 80.00	NNX
2	BOOTLID SEALANT	1	\$ 100.00	\$ 100.00	NNX
3	BOOTLID OUTER CHROME MOULDING CLIPS	1	\$ 60.00	\$ 60.00	NNX
4	BOOTLID INNER TRIM BOARD CLIPS	1	\$ 60.00	\$ 60.00	NNX
5	REAR BUMPER CLIPS	1	\$ 60.00	\$ 60.00	NNX
6	REAR BUMPER DIFFUSER CLIPS	1	\$ 60.00	\$ 30.00 60.00	NECV
7	REAR BUMPER REVERSE SENSOR SEAL	2	\$ 65.00	\$ 60.00 390.00	NECV
8	REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00	} NNX
9	REAR END PANEL TOP GARNISH CLIPS	1	\$ 60.00	\$ 60.00	
10	REAR FENDER SEALANT	1	\$ 100.00	\$ 100.00	NNX
11	REAR FENDER INNER TRIM BOARD CLIPS	1	\$ 60.00	\$ 60.00	NNX
12	REAR WINDSCREEN SEALANT	1	\$ 100.00	\$ 100.00	NNX
13	REAR WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00	NNX
14	REAR WINDSCREEN PRIMER & CLEANER	1	\$ 80.00	\$ 80.00	NNX
15	TAILLAMP SEAL	2	\$ 60.00	\$ 60.00 120.00	NECV
16	TAILLAMP CLIPS	2	\$ 60.00	\$ 120.00	NNX
17	REAR NUMBER PLATE W/CASING	2	\$ 80.00	\$ 160.00	NDX
SPECIAL NETT TOTAL :				\$ 150.00 1,790.00	

Nos.	LABOUR	S\$	
1	R&R BOOTLID COMPONENT	\$ 150.00	NNX
2	R&R REVERSE SENSOR	\$ 60.00 100.00	NECV
3	R&R REAR WINDSCREEN	\$ 250.00	NNX
4	DIAGNOSTIC RESET FAULT CODE	\$ 150.00 300.00	NECV
5	UPHOLSTERY	\$ 300.00	NNX
6	CHECK WIRING	\$ 30.00 100.00	NECV
7	CONDUCT WATER LEAK TEST	\$ 180.00	NNX
8	PANEL BEAT	\$ 800.00 1,400.00	} NNX
9	RUST PROOFING	\$ 200.00	
10	SPRAY PAINTING	\$ 600.00 1,400.00	
LABOUR TOTAL :		\$ 4,380.00	

27/11/2020 30/11/2020
 1400hrs 1417
 T. Lim T. Lim

Lump sum repair
 Repair days 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

PARTS TOTAL : \$ 16,124.97
 SPECIAL NETT TOTAL : \$ 1,790.00
 LABOUR TOTAL : \$ 4,380.00
GRAND TOTAL : \$ 22,294.97

PARTS 3915.61
 S/N 150.00
 LABOUR 1640.00
 5705.61
 1411.12
 4564.49

L/S 4550/2