

XINYA AUTO SERVICES PTE LTD

Add: BLK 1002, BUKIT MERAH LANE 3 #01-75, Singapore 159719 Tel: 6270 3481 Fax: 6278 7522
E-mail: xinyaauto@singnet.com.sg

Date : 26/11/2020

Address : TODDS PARTNERS PTE LTD
BLK 1002 BUKIT MERAH LANE 3
01-75
SINGAPORE 159719

Reference : TP 1264/11/20
Vehicle No : SGK 2176Y
Make/Model : HONDA ACCORD
Insurance Co. : CHINA TAIPING

RE : QUOTATION FOR REPAIRS TO SGK 2176Y FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

	QTY	AMT \$
1) REAR BUMPER <i>CR</i>	1	\$ 950.15
2) REAR BUMPER BRACKET <i>X EVC</i>	2	\$ 44.70 X
3) REAR BUMPER RETAINER <i>X SV</i>	2	\$ 52.30 X
4) TAILLAMP <i>CR @ 250</i>	2 <i>1pc</i>	\$ 500.00 <i>250</i>
5) BUMPER CLIPS <i>per</i>	10	\$ 48.00
NETT PRICE TOTAL		\$ 1,595.15 <i>1248.15</i>
LESS DISCOUNT 20%		\$ 319.03 <i>20%</i>
NETT PRICE TOTAL AFTER LESS		\$ 1,276.12 <i>998.52</i>
NETT PRICE TOTAL		\$ -
TOTAL PARTS COST		\$ 1,276.12

LABOUR AND MISCELLANEOUS CHARGES

1) TO REMOVE & REPLACE REAR BUMPER AND TO PANEL BEAT AND ALIGN.	\$ 600.00 <i>200</i> (03 days)
2) TO PUTTY & SPRAY PAINT REAR BUMPER AND END PANEL	\$ 200.00 <i>430</i> (2 PANELS)
3) TO CHECK & RECTIFY REAR WIRING	\$ 60.00 <i>30</i>
LABOUR TOTAL	\$ 860.00

TOTAL ESTIMATED REPAIR COST

\$ 2,136.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pass
Hp 90010018
2 days
4/5
01/12/2020 @ 1155
Resurvey after repair

998.52
430.00
1428.52
20%
1142.81
4/5-1150
2 days