



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel. 65684555 Fax. 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for Mr Lim Kai Zhong.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Includes account details like LAX00000 and credit terms.

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like 'RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID' and 'PAINT WORK SPRAY REAR END PANEL'.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE



CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Lim Kai Zhong Reg No/Reg Date SMF2116B / 13/08/201 Date In/Mileage / 0 Chassis No KNAF3416MK5013256 Engine No G4FGJH703409 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	27/11/2020/ 11:13	QUD	247 / DonBong	24924

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M HINGE ASSY-TRUNK LID,LH	1.00	97.00	20.00	77.60
M LOGO ASSY-KIA SUB	1.00	32.00	20.00	25.60
M EMBLEM-CERATO	1.00	28.00	20.00	22.40
M LAMP ASSY-CENTER GARNISH	1.00	690.00	20.00	552.00
M LAMP ASSY-REAR COMB INSIDE,LH	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE,RH	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE,LH	1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE,RH	1.00	675.00	20.00	540.00
M BRACKET ASSY-RR BPR SIDE UP,R	1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UP,R	1.00	31.00	20.00	24.80
M COVER-RR BUMPER UNDER,RH	1.00	33.00	20.00	26.40
M STAY-RR BUMPER LH	1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH	1.00	65.00	20.00	52.00
M ANTENNA ASSY-SMARTKEY	1.00	46.00	20.00	36.80
M BEAM-RR BUMPER	1.00	318.00	20.00	254.40
M BRACKET-RR BEAM UP,R MTG,LH	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UP,R MTG,RH	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR,CTR	1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG	2.00	6.00	20.00	9.60
M EXTN WIRING ASSY-BWS	1.00	207.00	20.00	165.60
M LAMP ASSY-SIDE T/SIGNAL,LH	1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL,RH	1.00	181.00	20.00	144.80
M COVER-RR BUMPER FOG LAMP,LH	1.00	19.00	20.00	15.20
M COVER-RR BUMPER FOG LAMP,RH	1.00	19.00	20.00	15.20
M CLIP	10.00	1.00	20.00	8.00
M GROMMET ASSY-SCREW	2.00	2.00	20.00	3.20
M COVER-RR BUMPER	1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR	1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER,LH	1.00	33.00	20.00	26.40

Estimate

SURVEYOR NAME : Steve CLKK
 SURVEYOR SIGNATURE : OO-NOT Afirm, Excess-?

DATE : 27/11/20, 11:00am

REMARKS : P/P, By CL sm
6 days
 Net 10,841.20
 7% GST on 10841.20 758.88
Total Payable 11,600.08

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts price is subject to insurance company
 • Third party survey is on a "without prejudice" basis
 • Validity of this estimate is 14 days
 • No illegal or unapproved parts or labor which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
 • Supplemental parts or labor which may be required after repair work has commenced. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or by cheque.
 • The rubber seal or other repair requiring the removal of the windscreen.

from date of quote. This is a computer generated document, no signature is required.
 GST. We would mention that the above estimate is based on our initial inspection and does not include repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or by cheque.
 the rubber seal or other repair requiring the removal of the windscreen.