



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay/a Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date : 11/25/2020

Total Pages : 2

TO:

China Taiping Insurance (S) Pte Ltd
3 Anson Rd, #16-00 Springleaf Tower
Singapore 079909

Our Customer : Global Advance Leasing

Vehicle No : **SJN9695T**

Model : TOYOTA / COROLLA AXIO 1.5X A

Manufacture Year : 2008

Date of Accident : 11/23/2020

Total Estimate Repair Days : 14

Attn : Motor Claim Department

Email : claimsdept@sg.cntaiping.com

Re: Repair Estimate For Own Damage Claim DMHCSNA00006592000

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper	1	\$220.00	\$220.00	Dis ✓
2	Front bumper clips	10	\$1.50	\$15.00	rec ✓
3	Front bumper fog lamp cover	1	\$30.00	\$30.00	11 X
4	RH headlamp	1	\$220.00	\$220.00	320 ✓
5	RH headlamp panel	1	\$90.00	\$90.00	RX
6	RH front fender	1	\$230.00	\$230.00	Dis ✓
7	RH front fender inner cowl	1	\$70.00	\$70.00	Torn ✓
8	RH front fender inner cowl clips	8	\$1.50	\$12.00	rec ✓
9	Wiper tank	1	\$50.00	\$50.00	De ✓
10	Rear bumper	1	\$180.00	\$180.00	Dis ✓
11	Rear bumper clips	10	\$1.50	\$15.00	rec ✓
12	RH rear bumper side retainer	2	\$38.00	\$76.00	Dis ✓
13	Rear bumper reverse sensor	1 set	\$380.00	\$380.00	X Torn RT
14	End panel	1	\$170.00	\$170.00	R
15	RH taillamp	1	\$130.00	\$130.00	320 ✓
16	RH rear fender	1	\$320.00	\$320.00	320 ✓
17	RH rear fender air vent	1	\$25.00	\$25.00	7w ✓
18	RH rear fender inner trim	1	\$140.00	\$140.00	11 X
19 Rec	Floor panel	1	\$280.00	\$280.00	RX
20 Rec	Floor board	1	\$200.00	\$200.00	wagon ✓
21	RH tools compartment pocket	1	\$45.00	\$45.00	De ✓
22	Rear axles	1	\$780.00	\$780.00	Seat/Tw ✓
23	RH rear absorber	1	\$70.00	\$70.00	tm ✓
24	RH rear wheel bearing with hub	1	\$180.00	\$180.00	22 ✓
25	RH front knuckle arm	1	\$140.00	\$140.00	Ref ✓
26	RH front wheel bearing	1	\$35.00	\$35.00	Ref ✓
27	RH front lower arm	1	\$75.00	\$75.00	17 X
28	RH front absorber	1	\$140.00	\$140.00	17 X
29	RH front anti roll bar linkage	1	\$60.00	\$60.00	17 X
30	Exhaust box	1	\$380.00	\$380.00	Dis ✓
31	Exhaust box mounting (front)	1	\$18.00	\$18.00	Torn ✓
32	Exhaust box mounting (rear)	1	\$18.00	\$18.00	Torn ✓
33	Exhaust box heat shield	1	\$100.00	\$100.00	cm ✓
34	Exhaust pipe (centre)	1	\$650.00	\$650.00	RX
35	Petrol tank heat shield	1	\$220.00	\$220.00	RX
36	Windscreen moulding	1	\$60.00	\$60.00	rec ✓
	Sub Total			\$5,824.00	
	Cost Plus 10%			\$582.40	
	Sub Total 1			\$6,406.40	
B.	Spare Parts (S/Nett)				
1	Windscreen sealant	2	\$25.00	\$50.00	rec 42



GARAGE

KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

2	Windscreen Primer	1	\$18.00	\$18.00	✓
			Sub Total 2	\$68.00	
			Total Spare Parts	\$6,474.40	
C.	Labour				
1	To panel beat, knock and straighten front and rear damaged portion, cut & weld damage panel. To adjust and realign the same		\$1,800.00		1200
2	To remove and refit rear windscreen		\$150.00		120
3	To install parking sensor		\$120.00		11X
4	To check all lighting & wiring		\$120.00		30
5	To rust proof all affected areas		\$180.00		21X
6	To drop rear undercarriage		\$380.00		220
7	To remove upholstery in order to replace RH rear fender		\$180.00		80
8	to putty and spray paint all affected areas		\$2,100.00		1500
9	To do wheel alignment		\$80.00		60
10	To remove and replace rear exhaust		\$120.00		50
11	Labour to repair rear seat panel		\$180.00		11X
12	Labour to remove upholstery (seat) to repair seat panel		\$120.00		80
13	Labour to drop and replace front undercarriage		\$280.00		120
			Total Labour	\$5,810.00	
			Total Repair Cost	\$12,284.40	3460
				12553.90	
* The above quoted are exclusive of GST.					

Yours faithfully,

Darla
f KT Garage Pte Ltd

Not Authorized
2/11/20
n/s 36000
Thoughtful Attorney
10 days
Excess 4500

Surveyor's Details	
Name	mercus mke
Contact	90096608
Survey Date	27/11/20
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	✓

DATE	Remark From MR TAN
	Please arrange for survey asap

Auto Consultants hence notify

Buyer of the following:

- 1. The vehicle is under repair.
- 2. The vehicle is under repair.
- 3. The vehicle is under repair.
- 4. The vehicle is under repair.
- 5. The vehicle is under repair.
- 6. The vehicle is under repair.
- 7. The vehicle is under repair.
- 8. The vehicle is under repair.
- 9. The vehicle is under repair.
- 10. The vehicle is under repair.

Acknowledged by Repairer

Signature

Date

5/NS8

18/11/20
90096608
90096608



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date : 10/12/2020

Total Pages : 2

TO: China Taiping Insurance (S) Pte Ltd
3 Anson Rd, #16-00 Springleaf Tower
Singapore 079909

Our Customer : Global Advance Leasing

Vehicle No : **SJN9695T**

Model : TOYOTA / COROLLA AXIO 1.5X A

Manufacture Year : 2008

Date of Accident : 11/23/2020

Total Estimate Repair Days : 14

Attn : Motor Claim Department
Email : claimsdept@sg.cntaiping.com

Re: Supplementary Repair Estimate For Own Damage Claim DMHCSNA00006592000

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper side retainer RH	1	\$25.00	\$25.00	sent/cr ✓
2	Radiator spare tank	1	\$50.00	\$50.00	✓
3	Front bumper beam	1	\$80.00	\$80.00	sent ✓
4	Rear bumper bracket RH	1	\$25.00	\$25.00	✓
5	RH taillamp bracket RH	1	\$35.00	\$35.00	✓
6	Wheel cap	1	\$30.00	\$30.00	✓
Sub Total				\$245.00	
Cost Plus 10%				\$24.50	
Sub Total 1				\$269.50	
Total Repair Cost				\$269.50	
* The above quoted are exclusive of GST.					

Yours faithfully,

Darla
f KT Garage Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

DATE	Remark From MR TAN
	Please arrange for survey asap