

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20013117/TQF3E2

Date: 06/04/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : SBS6872L Insured Vehicle No : SHA1214T
Date of Loss: 23/11/2020 Nature of Claim: TP Claim No: MCT20110367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6872L**
Make & Model: MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO Engine No: 902926C1084772
ABS (A)
Reg. Date: 30/04/2015 (Man. Year: 2014) Chassis No: WEB62808323128572
Colour: Multi-colour Odometer: 351970 km
Engine Capacity: 6374 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8/8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/11/2020
Date Inspected: 27/11/2020 Inspected At: SBS Transit Ltd (YCK)
3 Yio Chu Kang Crescent
Singapore 786010
Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Apr 2022)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SBS6872L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >