

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0919/2020/NS
DATE : 26-Nov-20
WIP : 58985

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian

13 days - ok - jb - 20 Jan 20

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LEE CHI KIN
ADDRESS : 75 JURONG EAST STREET 13
#19-01
SINGAPORE 609652
TELEPHONE : HP +65 97837778
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800012233
VEHICLE NO : **SLW 3022 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 6/2/2018
ENGINE NO : CHZ 624423
CHASSIS NO : WAUZZZ8V4J1037613
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Nov-20
PLACE OF ACCIDENT : JURONG EAST CENTRAL CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3022 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	280.00 \$	280.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	600.00 \$	600.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00 \$	400.00
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS.	S/N \$	200.00 \$	150.00
5	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	280.00 \$	280.00
SUB TOTAL LABOUR CHARGES		:	\$ 1,760.00	\$ 1,710.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3022 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 1,710.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,400.00	\$ 1,400.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	\$ 1,400.00
8	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER AND RHS REAR INNER SIDE PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,000.00	\$ 3,500.00
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR ENTRANCES, RHS SILL PANEL, RHS SIDE INNER PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$	5,800.00	\$ 3,025.00
10	TO RENEW RHS RER RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT.	S/N \$	520.00	\$ 280.00
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 18,072.00	\$ 11,507.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3022 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER		\$ 1,944.00	
2	REAR BUMPER FIXING PARTS		\$ 191.00	
3	REAR BUMPER GUIDE SECTION - LH/RH	2	\$ 32.00	
4	REAR BUMPER LOCKING MECHANISM	2	\$ 59.00	
5	REAR BUMPER SPOILER		\$ 234.00	
6	REAR LIGHT REFLECTOR - RH		\$ 41.00	
7	REAR BUMPER GUIDE SECTION - RH		\$ 66.00	
8	REAR FENDER - RH		\$ 2,305.00	\$ 1,844.00
9	C-PILLAR REINFORCEMENT - RH LOWER		\$ 191.00	
10	REAR WINDSCREEN		\$ 805.00	\$ 643.60
11	SIDE WINDOW - RH		\$ 563.00	\$ 450.40
12	PRIMER		\$ 19.00	\$ 14.96
13	WHEEL HOUSING LINER		\$ 237.00	
14	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
15	WHEEL SPOILER - RH REAR		\$ 35.00	
16	REAR DOOR - RH		\$ 2,494.00	\$ 1,995.20
17	REAR DOOR OUTER SEAL - RH	NEC	\$ 159.00	\$ 126.80
18	BONDING AGENT	NEC	\$ 47.00	
19	CLEANING SOLUTION	NEC	\$ 65.00	
20	REAR DOOR CATCH		\$ 93.00	
SUB TOTAL SPARE PARTS		:	\$ 9,668.00	\$ 5,074.96

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3022 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
				\$ 5,074.96
	<i>c/f</i>			
21	EXTERIOR DOOR HANDLE - RH		\$ 359.00	\$ 286.80
22	DOOR HANDLE HOUSING - RH		\$ 51.00	
23	REAR ALUMINIUM RIM - RH		\$ 699.00	\$ 558.80
24	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
25	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
26	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
27	STONE CHIP	S/N	\$ 180.00	\$ 180.00
28	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
29	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
30	SUNDRIES		\$ 300.00	\$ 83.52
TOTAL SPARE PARTS		:	\$ 12,157.00	\$ 7,084.08
TOTAL LABOUR CHARGES		:	\$ 18,072.00	\$ 11,507.00
GRAND TOTAL		:	\$ 30,229.00	\$ 18,591.08

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT