



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0919/2020/NS
DATE : 26-Nov-20
WIP : 58985

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LEE CHI KIN
ADDRESS : 75 JURONG EAST STREET 13
#19-01
SINGAPORE 609652
TELEPHONE : HP +65 97837778
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800012233
VEHICLE NO : **SLW 3022 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 6/2/2018
ENGINE NO : CHZ 624423
CHASSIS NO : WAUZZZ8V4J1037613
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Nov-20
PLACE OF ACCIDENT : JURONG EAST CENTRAL CARPARK



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3022 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	280.00	✓
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	600.00	✓
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS.	S/N \$	200.00	150 ✓
5	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	280.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 1,760.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3022 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00 ✓	
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	
8	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER AND RHS REAR INNER SIDE PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,000.00	3500
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR ENTRANCES, RHS SILL PANEL, RHS SIDE INNER PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 5,800.00	3025 Fender and related Panels: 3.5 x 550 = 1925 Door: 550 Bumper: 550 3025
10	TO RENEW RHS RER RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT.	S/N \$ 520.00	280 = 240 + 40
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 18,072.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3022 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Regis</i>		\$ 1,944.00	+
2 REAR BUMPER FIXING PARTS		\$ 191.00	+
3 REAR BUMPER GUIDE SECTION - LH/RH	2	\$ 32.00	+
4 REAR BUMPER LOCKING MECHANISM	2	\$ 59.00	+
5 REAR BUMPER SPOILER		\$ 234.00	+
6 REAR LIGHT REFLECTOR - RH		\$ 41.00	+
7 REAR BUMPER GUIDE SECTION - RH		\$ 66.00	+
8 REAR FENDER - RH <i>Dented</i>		\$ 2,305.00	✓
9 C-PILLAR REINFORCEMENT - RH LOWER		\$ 191.00	?
10 REAR WINDSCREEN <i>2 New</i>		\$ 805.00	✓
11 SIDE WINDOW - RH		\$ 563.00	✓
12 PRIMER <i>new</i>		\$ 19.00	✓
13 WHEEL HOUSING LINER <i>new</i>		\$ 237.00	+
14 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$ 88.00	+
15 WHEEL SPOILER - RH REAR <i>new</i>		\$ 35.00	+
16 REAR DOOR - RH <i>Dented</i>		\$ 2,494.00	✓
17 REAR DOOR OUTER SEAL - RH <i>new</i>	NEC	\$ 159.00	✓
18 BONDING AGENT	NEC	\$ 47.00	?
19 CLEANING SOLUTION	NEC	\$ 65.00	?
20 REAR DOOR CATCH		\$ 93.00	?
SUB TOTAL SPARE PARTS	:	\$ 9,668.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3022 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 EXTERIOR DOOR HANDLE - RH <i>lit</i>		\$ 359.00	✓
22 DOOR HANDLE HOUSING - RH <i>not a</i>		\$ 51.00	✗
23 REAR ALUMINIUM RIM - RH <i>lit</i>		\$ 699.00	✓
24 REAR WINDSCREEN SEALANT	S/N	\$ 200.00	✓
25 1/4 GLASS SEALANT	S/N	\$ 100.00	✓
26 METAL FILLER POWDER	S/N	\$ 280.00	✓
27 STONE CHIP	S/N	\$ 180.00	✓
28 CAVITY WAX	S/N	\$ 140.00	✓
29 ACRYLIC SEALANT	S/N	\$ 180.00	✓
30 SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 12,157.00	
TOTAL LABOUR CHARGES	:	\$ 18,072.00	
GRAND TOTAL	:	\$ 30,229.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Adrian Lj
: 27/11/20

: Not Authorised, 13 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT