

ASS. REC. BY:

Tougher

REF:

CC3/ Aug 20013/23/T10/83

ASSIGNMENT

GE 2030 July

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100273092Claims No. 363981320289Sum Insured: _____ Excess: 2000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☒	☒

Bal. or Market Value: 477K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: George

Vehicle: IN / OUT

Veh No: 3JB118R Yr Regn: 2011, Jan

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi S3 Sportback c.c. 1984Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 21857 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W447278P05.17072264

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45R19R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 21/11/20 D.O.I. 27/11/20Survey held at Premium BenoiDes. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Final fig \$24,357.96

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. / C. _____



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0907/2020/NS
DATE : 24-Nov-20
WIP : 58547

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS MONIQUE GOH
ADDRESS : 21 SELETAR COURT
SINGAPORE 807189
TELEPHONE : HP +65 94351052
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100273092-08
VEHICLE NO : **SJB 118 R**
MODEL CODE : AUDI S3 SB 2.0 TFSI QU 8P
MODEL YEAR : 10/1/2011
ENGINE NO : CDL 040855
CHASSIS NO : WAUZZZ8P0BA072264
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Nov-20
PLACE OF ACCIDENT : ALONG CTE (BEFORE AMK AVE 1)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 118 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 700.00	350.500
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	? ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	1250.2625
SUB TOTAL LABOUR CHARGES		: \$ 7,080.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 118 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER. ✓ ✓	\$ 3,000.00	1650 ✓
6	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	✓ ✓
7	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 ✓
8	TO RESPRAY REAR BUMPER.	\$ 900.00	550 ✓
9	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 12,694.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 118 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER		\$ 2,467.00	de ✓ 1973.60
2 FRONT BUMPER FACING PARTS		\$ 179.00	neu ✓ X nn
3 FRONT BUMPER CARRIER		\$ 663.00	bt ✓ 530
4 FRONT BUMPER SHOCK ABSORBER - LH/RH	2	\$ 432.00	? 172.80 de ✓
5 FRONT BUMPER GUIDE SECTION - LH/RH	2	\$ 76.00	? X nn
6 FRONT BUMPER SPOILER - LOWER CENTRE		\$ 379.00	? 303.20 de ✓
7 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 192.00	? X nn
8 FRONT BUMPER FOAM FILLER PIECE		\$ 128.00	de ✓ 102
9 WEBBING	NEC	\$ 13.00	neu ✓ 9.68
10 PLASTIC ADHESIVE	NEC	\$ 55.00	neu ✓ 44
11 PLASTIC MATERIAL BONDING AGENT	NEC	\$ 57.00	neu ✓ 45.36
12 PLASTIC CLEANER	NEC	\$ 32.00	neu ✓ 25.52
13 RADIATOR GRILLE		\$ 2,122.00	ann ✓ 1840
14 S3 INSCRIPTION		\$ 122.00	neu ✓ 97.60
15 FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2	\$ 650.00	X 260 de ✓
16 SIGNAL HORN - LOW/HIGH TONE	2	\$ 446.00	? X nn
17 SPRING SHACKLE		\$ 66.00	? X nn
18 FRONT FENDER - LH		\$ 750.00	Rx
19 FRONT FENDER ATTACHMENT PARTS		\$ 48.00	X nn
20 FRONT FENDER BRACKET - REAR		\$ 49.00	X nn
SUB TOTAL SPARE PARTS	:	\$ 8,926.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 2661 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT FENDER BRACKET - CENTRE		\$ 49.00	X	} X nn
22 FRONT FENDER BRACKET - FRONT		\$ 49.00	X	
23 FRONT FENDER BRACE - LH		\$ 53.00	X	
24 WHEEL HOUSING LINER - OUTER		\$ 167.00	X	
25 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 72.00	X	
26 WHEEL HOUSING LINER - OUTER		\$ 167.00	X	
27 WHEEL HOUSING LINER - INNER		\$ 128.00	X	
28 WHEEL HOUSING LINER - INNER		\$ 128.00	X	}
29 WHEEL SPOILER - LH/RH	2	\$ 112.00	X	
30 BONNET		\$ 2,373.00	bf -	1898.40
31 BONNET ATTACHMENT PARTS		\$ 96.00	nei -	X nn
32 BONNET LID HINGE - LH/RH	2	\$ 114.00	X	} nn
33 BONNET CATCH HOOK		\$ 92.00	X	
34 BONNET LID LOCK		\$ 212.00	X	
35 LID LOCK MICRO SWITCH		\$ 110.00	X	
36 BONNET LOCK COVER - UPPER FRONT		\$ 51.00	?	40.16 de /
37 HEADLIGHT MOUNTING - LH/RH	2	\$ 234.00	?	187.20 cur
38 HEADLIGHT - LH/RH	2	\$ 4,006.00	LH - cur / RH - ?	cur 3204.80
39 LIFT CYLINDER - LH/RH	2	\$ 402.00	?	X nn
40 LIFT CYLINDER HOSE	5	\$ 184.00	?	X nn
SUB TOTAL SPARE PARTS	:	\$	17,725.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 2661 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 LOCK CARRIER		\$ 971.00	? 776.80 net
42 EXTERNAL TEMPERATURE SENSOR		\$ 58.00	? X net
43 READY MIX COOLANT		\$ 91.00	? 72.32 net
44 AIRCON CONDENSER		\$ 515.00	bt ✓ photo 41.60
45 RADIATOR AIR GUIDE - LH/RH	2	\$ 78.00	? plus 676 de ✓
46 CAUTION SIGN STICKER	NEC	\$ 14.00	net ✓ 10.80
47 AIRCON STICKER	NEC	\$ 18.00	net ✓ 13.84
48 REAR BUMPER		\$ 2,300.00	de 1840
49 REAR BUMPER FIXING PARTS		\$ 132.00	X net
50 REAR BUMPER SPOILER - LOWER CENTRE		\$ 1,177.00	? plus X net
51 REAR BUMPER COVER - UPPER		\$ 59.00	? X net
52 REAR REINFORCEMENT BEAM		\$ 620.00	X
53 REAR BUMPER BRACKET - LH/RH	2	\$ 26.00	X
54 REAR BUMPER GUIDE SECTION - LH/RH INNER	2	\$ 132.00	X
55 REAR PARKING AID SENSOR	2	\$ 500.00	? X
56 FRONT NO PLATE	S/N	\$ 60.00	bt 60
57 SUNDRIES		\$ 400.00	? 81.12 net ✓
TOTAL SPARE PARTS	:	\$ 33,802.00	
TOTAL LABOUR CHARGES	:	\$ 12,694.00	
GRAND TOTAL	:	\$ 46,496.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

*Taufik Ikhanto van.
Taufik 97495747
27/11/20 C 145p-
Not Authorise Ex: hbq
8 days
Resurvey before paint*

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0907/2020/NS
4-Dec-20
George Wong
1 of 1
SJB 118 R
Audi S3 SB 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

- | | | | |
|---|-------------------------------|-------------|---------|
| 1 | FRONT AIR GUIDE <i>cr</i> | \$ 83.00 | 66 |
| 2 | ADDITIONAL RADIATOR <i>bt</i> | \$ 1,064.00 | 851.20 |
| 3 | RADIATOR <i>bt</i> | \$ 1,263.00 | 1010.40 |

GRAND TOTAL

\$ 2,410.00

For Premium Automobiles Pte Ltd

Ratna
Per
08/12/2020



Authorized Signature

*Subject to insurance
approval
Xtra - 3 days*



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0907/2020/NS

4-Dec-20

George Wong

1 of 1

SJB 118 R

Audi S3 SB 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT CONNECTING PIPER- RIGHT LOWER	\$ 341.00	✓ 272.40
2	FRONT PRESSURE HOSE- LH LOWER	\$ 158.00	✓ 126.40
	GRAND TOTAL	\$ 499.00	

For Premium Automobiles Pte Ltd

Adrian L
14/12/20
888

Authorised Signature