

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0907/2020/NS
DATE : 24-Nov-20
WIP : 58547

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Taufikh,

We took 16 days to repair this vehicle.

22/02/2021 - Carrine

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS MONIQUE GOH
ADDRESS : 21 SELETAR COURT
SINGAPORE 807189
TELEPHONE : HP +65 94351052
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100273092-08
VEHICLE NO : **SJB 118 R**
MODEL CODE : AUDI S3 SB 2.0 TFSI QU 8P
MODEL YEAR : 10/1/2011
ENGINE NO : CDL 040855
CHASSIS NO : WAUZZZ8P0BA072264
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Nov-20
PLACE OF ACCIDENT : ALONG CTE (BEFORE AMK AVE 1)

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 118 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	\$ 280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 700.00	\$ 500.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	\$ 1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	\$ 2,625.00
SUB TOTAL LABOUR CHARGES		: \$ 7,080.00	\$ 4,605.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 118 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 4,605.00
5	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$ 3,000.00	\$ 1,650.00
6	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	\$ 280.00
7	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	\$ 500.00
8	TO RESPRAY REAR BUMPER.	\$ 900.00	\$ 550.00
9	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 12,694.00	\$ 7,969.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 118 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
1	FRONT BUMPER		\$ 2,467.00	\$	1,973.60
2	FRONT BUMPER FACING PARTS		\$ 179.00		
3	FRONT BUMPER CARRIER		\$ 663.00	\$	530.00
4	FRONT BUMPER SHOCK ABSORBER - LH/RH	2	\$ 432.00	\$	172.80
5	FRONT BUMPER GUIDE SECTION - LH/RH	2	\$ 76.00		
6	FRONT BUMPER SPOILER - LOWER CENTRE		\$ 379.00	\$	303.20
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 192.00		
8	FRONT BUMPER FOAM FILLER PIECE		\$ 128.00	\$	102.00
9	WEBBING	NEC	\$ 13.00	\$	9.68
10	PLASTIC ADHESIVE	NEC	\$ 55.00	\$	44.00
11	PLASTIC MATERIAL BONDING AGENT	NEC	\$ 57.00	\$	45.36
12	PLASTIC CLEANER	NEC	\$ 32.00	\$	25.52
13	RADIATOR GRILLE		\$ 2,122.00	\$	1,840.00
14	S3 INSCRIPTION		\$ 122.00	\$	97.60
15	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2	\$ 650.00	\$	260.00
16	SIGNAL HORN - LOW/HIGH TONE	2	\$ 446.00		
17	SPRING SHACKLE		\$ 66.00		
18	FRONT FENDER - LH		\$ 750.00		
19	FRONT FENDER ATTACHMENT PARTS		\$ 48.00		
20	FRONT FENDER BRACKET - REAR		\$ 49.00		
SUB TOTAL SPARE PARTS		:	\$ 8,926.00	\$	5,403.76



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 2661 M

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
	<i>c/f</i>			\$	5,403.76
21	FRONT FENDER BRACKET - CENTRE		\$ 49.00		
22	FRONT FENDER BRACKET - FRONT		\$ 49.00		
23	FRONT FENDER BRACE - LH		\$ 53.00		
24	WHEEL HOUSING LINER - OUTER		\$ 167.00		
25	WHEEL HOUSING LINER ATTACHMENT PART		\$ 72.00		
26	WHEEL HOUSING LINER - OUTER		\$ 167.00		
27	WHEEL HOUSING LINER - INNER		\$ 128.00		
28	WHEEL HOUSING LINER - INNER		\$ 128.00		
29	WHEEL SPOILER - LH/RH	2	\$ 112.00		
30	BONNET		\$ 2,373.00	\$	1,898.40
31	BONNET ATTACHMENT PARTS		\$ 96.00		
32	BONNET LID HINGE - LH/RH	2	\$ 114.00		
33	BONNET CATCH HOOK		\$ 92.00		
34	BONNET LID LOCK		\$ 212.00		
35	LID LOCK MICRO SWITCH		\$ 110.00		
36	BONNET LOCK COVER - UPPER FRONT		\$ 51.00	\$	40.16
37	HEADLIGHT MOUNTING - LH/RH	2	\$ 234.00	\$	187.20
38	HEADLIGHT - LH/RH	2	\$ 4,006.00	\$	3,204.80
39	LIFT CYLINDER - LH/RH	2	\$ 402.00		
40	LIFT CYLINDER HOSE	5	\$ 184.00		
SUB TOTAL SPARE PARTS		:	\$ 17,725.00	\$	10,734.32

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 2661 M

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
		<i>c/f</i>		\$	10,734.32
41	LOCK CARRIER		\$ 971.00	\$	776.80
42	EXTERNAL TEMPERATURE SENSOR		\$ 58.00		
43	READY MIX COOLANT		\$ 91.00	\$	72.32
44	AIRCON CONDENSER		\$ 515.00	\$	411.60
45	RADIATOR AIR GUIDE - LH/RH	2	\$ 78.00	\$	61.76
46	CAUTION SIGN STICKER	NEC	\$ 14.00	\$	10.80
47	AIRCON STICKER	NEC	\$ 18.00	\$	13.84
48	REAR BUMPER		\$ 2,300.00	\$	1,840.00
49	REAR BUMPER FIXING PARTS		\$ 132.00		
50	REAR BUMPER SPOILER - LOWER CENTRE		\$ 1,177.00		
51	REAR BUMPER COVER - UPPER		\$ 59.00		
52	REAR REINFORCEMENT BEAM		\$ 620.00		
53	REAR BUMPER BRACKET - LH/RH	2	\$ 26.00		
54	REAR BUMPER GUIDE SECTION - LH/RH INNE	2	\$ 132.00		
55	REAR PARKING AID SENSOR	2	\$ 500.00		
56	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
57	SUPPLEMENTARY		\$ 499.00	\$	398.80
58	SUPPLEMENTARY		\$ 2,410.00	\$	1,927.60
59	SUNDRIES		\$ 400.00	\$	81.12
TOTAL SPARE PARTS		:	\$ 36,711.00	\$	16,388.96
TOTAL LABOUR CHARGES		:	\$ 12,694.00	\$	7,969.00
GRAND TOTAL		:	\$ 49,405.00	\$	24,357.96

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-13/01/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315
Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0907/2020/NS

4-Dec-20

George Wong

1 of 1

SJB 118 R

Audi S3 SB 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT AIR GUIDE	\$ 83.00	\$ 66.00
2	ADDITIONAL RADIATOR	\$ 1,064.00	\$ 851.20
3	RADIATOR	\$ 1,263.00	\$ 1,010.40
GRAND TOTAL		\$ 2,410.00	\$ 1,927.60

For Premium Automobiles Pte Ltd

 Authorised Signature

**Supplementary Estimate 2**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.**Date****Service Advisor****Pages****Regn No****Model No**

PA/OD/0907/2020/NS

4-Dec-20

George Wong

1 of 1

SJB 118 R

Audi S3 SB 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT CONNECTING PIPER- RIGHT LOWER	\$ 341.00	\$ 272.40
2	FRONT PRESSURE HOSE- LH LOWER	\$ 158.00	\$ 126.40
GRAND TOTAL		\$ 499.00	\$ 398.80

For Premium Automobiles Pte Ltd

Authorised Signature