

ASS. REC. BY:

Steve

REF:

CS/AIG 200/3128/Eqf3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

2070106804

Claims No.

1846588350SG

Sum Insured:

Excess:


0/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

80K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

15

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

30/11/20@2.18pm revert to AIG via Merimen.

30/11/20@6.15pm Lois Chang informed C/A via Merimen.

01/12/20@10.14am Informed Kevin C/A & ex:\$600 by email.

01/12/20 Deeban informed ex:\$0/- thru email.

15/01/21@11.17am Confirmed with Ms Loi final fig \$18145.40, 15 days (Red \$2502, 12%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

15

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Rep. Formed:

MER-OD

Lump Sum / L.E. / C

18145.40



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12463/ZOLPAKAR BIN ABDUL KARIM Reg No/Reg Date SMT7826D / 17/07/202 Date In/Mileage 27/11/2020/ 0 Chassis No KNAF3416ML5069521 Engine No G4FGKH755670 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	28/11/2020/ 11:17	QUK	282 / Kevin Leong	25005			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3200.00
REPLACE FRT BUMPER, FRT LH FENDER, FRT LH DOOR, REAR LH FENDER, BONNET & AFFECTED AREA					400			2400
REPAIR ON REAR LH FENDER & LH ROCKER PANEL								
E PNT98000								2450.00
PAINT WORK ON FRT BUMPER, BONNET, FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER & LH ROCKER PANEL								
E PNT88000								120.00
TRANSFER FRONT LH DOOR ATTACHMENT TO NEW PANEL								
E PNT88000								120.00
TRANSFER REAR LH DOOR ATTACHMENT TO NEW PANEL								
M SUNDRY								40.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
TO TRANSFER FRT LH RIM INCLUDING BALANCING								
A 33900099								400.00
REPLACE FRONT UNDERCARRIAGE								
M SUNDRY								480.00
TO SUPPLY FRONT LH SPORT RIM								
M SUNDRY								380.00
TO SUPPLY FRONT LH WHEEL TYRE								
M SUNDRY								50.00
SUNDRIES								
M LAMP ASSY-HEAD,LH					1.00	1219.00	20.00	975.20
M KNUCKLE-FRONT AXLE,LH					1.00	350.00	20.00	280.00
M HUB ASSY-FR WHEEL					1.00	436.00	20.00	348.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12463/ZOLPAKAR BIN ABDUL KARIM Reg No/Reg Date SMT7826D / 17/07/202 Date In/Mileage 27/11/2020/ 0 Chassis No KNAF3416ML5069521 Engine No G4FGKH755670 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/11/2020/ 11:17	QUK	282 / Kevin Leong	25005
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M KNUCKLE-FRONT AXLE,LH		1.00	350.00	20.00	280.00
M GEAR ASSY-STEERING / BT		1.00	770.00	20.00	616.00
M LINK-STABILIZER / BT		1.00	72.00	20.00	57.60
M BAR ASSY-FR STABILIZER		1.00	238.00	20.00	190.40
M STRUT ASSY-FR,LH / BT		1.00	280.00	20.00	224.00
M INSULATOR ASSY-STRUT / MC		1.00	85.00	20.00	68.00
M BEARING-STRUT / MC		1.00	86.00	20.00	68.80
M PAD-FRONT SPRING,LWR / MC		1.00	23.00	20.00	18.40
M CROSSMEMBER COMPL		1.00	1156.00	20.00	924.80
M ARM COMPLETE-FR LWR,LH / BT		1.00	286.00	20.00	228.80
M STAY LH / BT		1.00	22.00	20.00	17.60
M PANEL ASSY-HOOD / DD		1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,RH		1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,LH		1.00	43.00	20.00	34.40
M PANEL-FENDER,LH / DD		1.00	430.00	20.00	344.00
M INSULATOR-FENDER LH		1.00	27.00	20.00	21.60
M PANEL ASSY-FRONT DOOR,LH / DD		1.00	1277.00	20.00	1021.60
M HINGE ASSY-FRONT DOOR,LH		1.00	30.00	20.00	24.00
M HINGE ASSY-DOOR LOWER,LH		1.00	27.00	20.00	21.60
M PANEL ASSY-REAR DOOR,LH / DD		1.00	1377.00	20.00	1101.60
M HINGE ASSY-REAR DOOR UPPER,LH		1.00	33.00	20.00	26.40
M HINGE ASSY-DOOR UPPER,LH		1.00	26.00	20.00	20.80
M PAD-HOOD INSULATING		1.00	156.00	20.00	124.80
M MOULDING ASSY-FRT DR FRAME,LH		1.00	37.00	20.00	29.60
M W/STRIP ASSY-FR DR BELT O/S LH		1.00	64.00	20.00	51.20
M W/STRIP ASSY-FR DR SIDE LH		1.00	102.00	20.00	81.60
M W/STRIP-FR DR BELT I/S LH		1.00	43.00	20.00	34.40
M MOULDING ASSY-RR DR FRAME,LH		1.00	44.00	20.00	35.20
M W/STRIP ASSY-RR DR BELT O/S LH		1.00	60.00	20.00	48.00
M W/STRIP ASSY-RR DR SIDE LH		1.00	102.00	20.00	81.60
M BLACK TAPE-FR DR RR,LH / MC		1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FR,LH / MC		1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FRAME RR OTR, / MC		1.00	8.00	20.00	6.40

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENION WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12463/ZOLPAKAR BIN ABDUL KARIM Reg No/Reg Date SMT7826D / 17/07/202 Date In/Mileage 27/11/2020/ 0 Chassis No KNAF3416ML5069521 Engine No G4FGKH755670 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	28/11/2020/ 11:17	QUK	282 / Kevin Leong	25005			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
					1.00	32.00	20.00	25.60
M	ORNAMENT-KIA NO.115	✓	ARC		1.00	95.00	20.00	76.00
M	GUARD ASSY-FRONT WHEEL, LH	✓	CR4		1.00	633.00	20.00	506.40
M	COVER-FR BUMPER	✓	BR		1.00	262.00	20.00	209.60
M	GRILLE-FRONT BUMPER	X			1.00	14.00	20.00	11.20
M	AIR DUCT-FR BUMPER, LH	X			1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG	✓	BR		1.00	1721.00	00.00	1721.00
M	NEW K3 2020 BODYKIT	X	R					

Estimate

Store (LKK) 00-161 Authm  
Excess - ?  
30/11/20 10-30am  
12 dys  
P/P  
By BIL sy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: Confirm & accepted by  
Date:

Nett 18,771.40  
7% GST on 18771.40 1314.00  
Total Payable 20,085.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.