

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013129/QGA3Q2
Date: 10/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	FBN9562M	Insured Vehicle No :	SHC3351G
Date of Loss:	25/11/2020	Nature of Claim:	TP
		Claim No:	MCT20110412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN9562M		
Make & Model:	HONDA FORZA 300, 279cc ABS CVT	Engine No:	NF07E2001123
Reg. Date:	14/01/2019 (Man. Year: 2018)	Chassis No:	ZDCNF08A0KF001187
Colour:	Silver	Odometer:	30620 km
Engine Capacity:	279 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-15	Rear Tyre Size:	120/70-15
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,999.00	1,512.00	487.00	24.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	225.00	90.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,314.00	1,737.00	577.00	24.94
+ GST 7.00/7.00% (S\$)	161.98	121.59	40.39	24.94
Nett Amount (S\$)	2,475.98	1,858.59	617.39	24.94
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	27/11/2020		
Date Inspected:	01/12/2020	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	2.0 days		

Adjuster: OI SUN PIN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 08 Apr 2021)**Parts:** N/A HONDA FORZA 300 279cc ABS CVT (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for FBN9562M)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*CLIP ,SNAP FITTING (PO)	Necessary	64.00 F	*30.00 F
2	1		*COVER RH FRONT SIDE	Scratched	278.00 F	*278.00 F
3	1		*COVER INNER	Scratched	325.00 F	*325.00 F
4	1		*COVER,R.BACK MIRROR	Scratched	66.00 F	*66.00 F
5	1		*COVER,R.FR .SIDE INNER	Cracked	195.00 F	*195.00 F
6	1		*MAT CYNOS GRAY METALLIC	Scratched	165.00 F	*165.00 F
7	1		*MIRROR COMP,R.BACK	Scratched	70.00 F	*70.00 F
8	1		*PROTEC COM,MUFFLER (B)	Not Necessary	105.00 F	*- F
9	1		*PROTECTOR A,MUFFLER	Not Necessary	220.00 F	*- F
10	1		*SEAL ,HING COVER RUBBER	Necessary	58.00 F	*58.00 F
11	1		*STEP,R.FLOOR	Serviceable	128.00 F	*- F
12	1		*VISOR SET ,FR.(WL)	Scratched	325.00 F	*325.00 F

F=Franchise part.

Total Parts (S\$)	1,999.00	1,512.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS	New	315.00	225.00
			Gross Labour Cost (S\$)	225.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >