

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0296/2020
DATE : 26-NOV-2020

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

ODR ⇒ Tanfikh
= (Ltk-Auto)

OWNER'S NAME : M/S SOUTH AIR-COND & REFRIGERATION PTE. LTD.
ADDRESS : BLK 2022 BUKIT BATOK ST 23
#02-164
S(659527)
TELEPHONE NO : 65600800

ZHR

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DMCVSNW00107222000
VEHICLE NO : GBK7247C
MODEL CODE : MVL2RDRE26KW3JBT-E
MODEL/YEAR : NISSAN NV350 PANEL VAN 5DR 2.5 5MT MY2019
ENGINE NO : YD25081023B
CHASSIS NO : JN1MC2E26Z0032430
MILEAGE : 1 KM
DATE IN : 26/11/2020
LIABILITY : 0.00
EXCESS CLAUSE : 500.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 23/11/2020

Recommend Repair 5days

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBK7247C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	.00
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120.00
3 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	.00
6 ZZ/001	CHECK LIGHTING	48.00	48.00
7 ZZ/002	TRANSFER MECHANISM PART FOR TAILGATE	80.00	80.00
8 ZZ/003	RENEW RR WINDSCREEN	250.00	250.00
9 ZZ/004	REPAIR RR END PANEL & RENEW RR BUMPER TAILGATE & RR END PANEL OUTER	1120.00	700.00
10 ZZ/005	S/PAINT RR BUMPER ,TAILGATE(1.5) & RR END PANEL	625.00	625.00
TOTAL LABOUR CHARGES		2788.00	1978.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBK7247C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	FACE-RR BUMPER	85022-3XA0A	667.20			OK
2	CLIP(1.3X10)	01553-05933	13.00			OK
3	BRKT-RR BMPR	85040-V200A	171.90			OK
4	DOOR BACK	K010M-3XBFA	1816.70			OK
5	SEALANT - W/SCREEN GLASS	SEALANT - 2			80.00	OK
6	RUBBER-DUM	G2G16-89900	63.80			OK
7	GLASS-TAIL GATE	90300-3XA0A	891.00			OK
8	LOCK & REMOCON	90500-5YE0A	287.10			X
9	EMBLEM-REAR	90890-JX00A	64.90			OK
10	EMBLEM-BACK DOO	90890-3XY0A	110.00			OK
11	SENSOR-REVERSE	SENSOR			250.00	OK
12	LABEL 70KM/H	SWD-70KM			10.00	OK
13	LABEL-8PAX	PAX-8			12.00	OK
14	SUNDRIES	NPN			20.00	OK
SUB TOTAL			3798.50	0.00	372.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			759.70	0.00	0.00	
GRAND TOTAL			3038.80	0.00	372.00	
OVERALL TOTAL			3410.80			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBK7247C

NETT ITEM	3798.50
LESS 20.00%)	-759.70
NETT AMOUNT	3038.80
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	372.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	372.00
TOTAL LABOUR CHARGES	1978.00
TOTAL SPARE PARTS CHARGES	3410.80
TOTAL CHARGES	5388.80
LESS EXCESS	500.00
TOTAL	4888.80
ADD 7 % GST	342.22
GRAND TOTAL	5231.02