

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 01 Dec 2020

Preliminary Advice

Vehicle No	: GBK7247C	Accident Date	: 23/11/2020
Make	: NISSAN NV350	Policy No.	: DMCVSNW00107222000
Assignment Date	: 30/11/2020	Excess	: S\$500.00
Date of Inspection	: 30/11/2020	Est. Duration of Repair	: 5
Inspection At	: TAN CHONG MOTOR SALES PTE LTD (BUKIT TIMAH) 911, BUKIT TIMAH ROAD SINGAPORE 589622		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,448.48
Revised Amount	:S\$	4,538.48
Check Items (Estimated)	:S\$	1,080.00
Total	:S\$	5,618.48

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	21,346.00
Salvage Value	:S\$	
Margin for Repair	:S\$	46,654.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :