

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts in a prominent manner
- Parts prices are subject to change
- Third party survey is an add'l cost
- No tie

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Supplementary & additional work is subject to final approval. Email: ryderautoworkshop@gmail.com Tel: 67418277 Fax: 67468277

KMHD84LCMJ47038/6.

Acknowledged by Repairer

ESTIMATE OF REPAIR

HYUNDAI ELANTRA AD 1.6

Veh# : SMD4645M

Signature:

Model:

GLS AT

(21/8/2018)

Accident Date : 27/11/20

TP Ergo

Xiao Chen

Location : LORNIE ROAD SLIP ROAD TOWARDS PIE TUA

3P:

GBB8988M (ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Replaced</i>	780.00	✓	-
2	10 pcs	Rear bumper clips <i>Replaced</i>	-	30.00	✓
3	1 pc	Rear bumper enforcement <i>Best</i>	420.00	-	-
4	1 pc	Rear bumper buzzer <i>Can be used</i>	140.00	✓	-
5	1 pc	Rear bumper lower diffuser <i>Discontinued</i>	260.00	✓	-
6	6pcs	Rear bumper lower diffuser clips <i>Replaced</i>	-	18.00	✓
7	2pcs	Rear bumper o/s & n/s reflector <i>Hit cut</i>	150.00	75	-
8	2 pcs	Rear bumper o/s & n/s retainer <i>Replaced</i>	202.80	+	-
9	1 pc	Rear boot cover <i>Replaced</i>	1,890.00	-	-
10	1 pc	Rear boot cover weatherstrip <i>Hit</i>	135.00	✓	-
11	1 pc	Rear boot cover emblem	106.40	-	-
12	1 pc	Rear boot cover Elantra emblem <i>Replaced</i>	79.20	✓	-
13	1 pc	Rear boot cover 'S' emblem	78.40	+	-
14	1 pc	Rear boot cover lock (upper) <i>Replaced</i>	150.00	✓	-
15	2 pcs	Rear boot cover o/s & n/s reflector <i>Can be used</i>	870.00	✓	-
16	2 pcs	Rear o/s & n/s tail-lamp <i>Hit cut</i>	960.00	980	-
17	1 pc	Rear end panel <i>Replaced</i>	435.00	✓	-
18	1 pc	Rear end panel inner trim <i>Replaced</i>	105.00	✓	-
19	1 pc	Rear spare wheel board cover <i>Replaced</i>	300.00	✓	-
20	2 pcs	Rear bumper reverse sensor <i>Replaced</i>	-	280.00	200
21	1 pc	Rear reg. no. plate <i>Green</i>	-	45.00	+
22	1 pc	Rear reg. no. plate bracket	-	29.00	+
23	1 pc	Rear n/s under cover <i>Torn</i>	90.00	✓	-
Sub-Total:			7,061.80	402.00	0.00
			20%	0%	0%
After Less %:			5,649.44	402.00	0.00
Labour					
1		To dismantle, straighten & welding.	1,200.00	800	-
2		To spray painting.	800.00	700	-
3		To remove & replace rear reverse sensor.	50.00	✓	-
4		To check wiring.	50.00	30	-
5		To re-seal anti-rust.	80.00	60	-
Sub-Total:			2,180.00		
Total:			8,231.44		

470

295

1785

45

48

56

792

5661

km 20%: 452880

S.N: 248

Advance
R/S 30/11/20
06 days.

1640

Total: 641680

L/S: 5.1K.

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



AL 8778 1999

24 hr accident call

SMD4645M ESTIMATEPg1

Mobil 1

