



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI20013139/Gny3e2	
			Date: 28/12/2022	
			Code: UOI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SJU 6611T
	<b>Policy No.</b>	DHOM110171791900	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	M11D11392012	<b>Excess (\$)</b>	600.00
	<b>Assign From</b>	JOSEPHINE WONG	<b>Assign Date</b>	30/11/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA ALTIS 1.6	<b>c.c</b>	1598
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
	<b>Chassis No.</b>	MR053ZEE106160497	<b>Colour</b>	BLACK
	<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	WEST LAKE	5 mm
	<b>L/H Front Tyre</b>	195/65 R15	WEST LAKE	5 mm
	<b>R/H Rear Tyre</b>	195/65 R15	WEST LAKE	5 mm
	<b>L/H Rear Tyre</b>	195/65 R15	WEST LAKE	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	22/11/2020	<b>Inspection Date</b>	30/11/2020
	<b>Survey held at</b>	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$26,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	