



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Kuek Hock Keng  BLK 688C CHOA CHU KANG CRESCENT #04-118 SINGAPORE 683688  Contact No Mobile: 94563050	Cust No/Name /Mr Kuek Hock Keng Reg No/Reg Date SMH5763C / 28/01/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001041 Engine No 3A92UHN8065 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	30/11/2020/ 11:00	BLC	442 / CocoLu	60206		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1350.00
RENEW REAR BUMPER, BOOTLID, REPAIR REAR AIRDAM, REAR END PANEL 450							60.00
E PNT88000							1400.00
REMOVE & INSTALL PARKING SENSOR							40.00
E PNT98000							30.00
SPRAY PAINT FOR REAR AIRDAM, REAR END PANEL, REAR BUMPER 350							120.00
BOOTLID. I							20.00
M SUNDRY							100.00
c&c LOGO							
A 54900099							
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							
Sundry							
E PNT88000							
REMOVE & INSTALL REAR AIRDAM				1.00	748.00	00.00	748.00
M FACE,RR BUMPER	DEF			1.00	28.00	00.00	28.00
M BRACKET,RR BUMPER,RH	BR			1.00	28.00	00.00	28.00
M BRACKET,RR BUMPER,LH	X NN			1.00	791.00	00.00	791.00
M PANEL,TRUNK LID	00			1.00	203.00	00.00	203.00
M HINGE,TRUNK LID,RH	X NN			1.00	203.00	00.00	203.00
M HINGE,TRUNK LID,LH	X NN			1.00	21.00	00.00	21.00
M MARK,ATTRAGE	NC			1.00	69.00	00.00	69.00
M MARK,THREE-DIA	NC			1.00	66.00	00.00	66.00
M TRIM,RR END	X NN						

Estimate

30/11/20, 4.30pm

Steve (CLKK) 00 - NM Authr

Excess - ?

4 - 5 days

Estimate

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplier's signature and company stamp  
is subject to final approval from Insurance Company

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

7% GST on Net 5,277.00 369.39

Total Payable 5,646.39