

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☒ Own Damage
☐ 3rd Party
☐ Windscreen

Ins Company : AWAC
Excess : TBA
Date of Accident : 21.11.2020
Suggested Days of Repair : 6 DAY

Vehicle No. : SLW6398A
Make & Model : VOLKSWAGEN / PASSAT VARIANT R-L TSI HUD
Year of Manufacture : 2017
Chassis No. : WVWZZZ3CZHE201421
Engine No. : CHH209768
Policy No. : BVFPSB0006822008
Time of Accident : 10.45 A.M

In-house Vehicle Assessor

Name : Wong Chee Wei
Signature :
Contact No : 68676919
HP : 97239882

Repair Estimates

Parts (a) Cost / List Price Items \$5,262.00
Plus/Less 10 % \$526.20
(b) Nett Price Items
Less %
(c) Special Nett Items \$205.00
Total Parts Cost (Appendix A) \$5,993.20
Labour (Appendix B) \$2,060.00
Total Repair Cost \$8,053.20

8273.20

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4+1=5 days P/P

(c) Resurvey : Required / Not Required

(d) Excess : \$ 500 / REPAIR / Resurvey before paint

(e) Signature of surveyor : Fel Date: 01/12/2020

45 Pandan Road S (609386)
Tel: 68676919 Fax: 62626950, 68676903

Labour

Submit By : : Wong Chee Wei

Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)
Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

Vehicle No. : SLW6398A Submit By : Wong Chee Wei
 Make & Model : PASSAT VARIANT R-LINE 2.0 Year Manufacture : 2017
 Chassis No. : VWVZZZ3CZHE201421 Engine No. : CHH209768
OD

S/Order

S/No	Part Description	Qty	Cost Price		Nett Price	List Price	S- Nett Price	Disposition By Surveyor
			original	OEM				
1	FRONT BUMPER <i>de</i>	1	\$650.00					
2	FR BUMPER CLIP <i>de</i>	10	\$30.00					
3	FR BUMPER SIDE RETAINER,LH <i>X sue</i>	1	\$26.00					
4	FR BUMPER SIDE RETAINER,RH <i>X sue</i>	1	\$26.00					
5	FR BUMPER UPPER BRACKET,LH <i>? x sue</i>	1	\$30.00					
6	FR BUMPER UPPER BRACKET ,RH <i>? x sue</i>	1	\$30.00					
7	FR BUMPER SPONGE <i>? x sue</i>	1	\$80.00					
8	FR BUMPER REINFORCEMENT <i>? fsu</i>	1	\$250.00					
9	FRONT GRILLE CHROME <i>cm</i>	1	\$680.00					
10	LOGO - FR <i>cm</i>	1	\$65.00					
11	LEFT HEADLAMP <i>? cm</i>	1	\$950.00					
12	LEFT HEADLAMP CHROME MOULGING <i>? x sue</i>	1	\$40.00					
13	RIGHT HEADLAMP <i>? x sue</i>	1	\$950.00					
14	RIGHT HEADLAMP CHROME MOULDING <i>? x sue</i>	1	\$40.00					
15	FRONT SUPPORT PANEL <i>? repair x</i>	1	\$450.00					
16	BONNET <i>bt</i>	1	\$750.00					
17	BONNET INSULATOR CLIP <i>de</i>	15	\$45.00					
18	BONNET LOCK <i>X sue</i>	1	\$120.00					
19	BONNET FR SEAL,RH <i>de</i>	1	\$25.00					
20	BONNET FR SEAL ,LH <i>de</i>	1	\$25.00					
21	FRONT NO.PLATE <i>de</i>	1					\$45.00	
22	RADIATOR COOLANT <i>? xnn</i>	1					\$60.00	
23	AIR CON GAS & OIL <i>? xnn</i>	1					\$100.00	
24		1						
25		1						
26		1						
27		1						
28		1						
29		1						
30		1						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.