

ASS. REC. BY:

Sterc

REF:

CS/AIG 20013143/Eqf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 29320

Yr Regn:

7/11/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c

1591

Colour:

Red

A/C:

Insured / Std / NI / N

Sp. Reading

21.28

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNAF 5416 MKS 252954

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

29/11/20

D.O.I.

30/11/20

Survey held at

Cycle & carriage

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

Frt RH.

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-84K

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Rep. Form:

Lump Sum / L.E. /



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11454/LAI ZHEN NAN (LI ZHENNAN) Reg No/Reg Date SMQ29320*ECB1/ 07/11/201 Date In/Mileage 30/11/2020/ 0 Chassis No KNAF5416MK5052954 Engine No G4FGKH749533 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	30/11/2020/ 13:18	QUK	282 / Kevin Leong	25072			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, BOTH FRT FENDER & AFFECTED AREA 470 REPAIR ON FRT LH DOOR X					1600			2400.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER & FRT LH DOOR 880 480					40			80.00
M SUNDRY PERFORM RUST PREVENTION								30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								400.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA 80X11					1.00	2210.00	20.00	1768.00
M LAMP ASSY-HEAD,LH / BR					1.00	2210.00	20.00	1768.00
M LAMP ASSY-HEAD,RH / BR					1.00	146.00	20.00	116.80
M RESERVOIR & PUMP ASSY-WASHER / BR					1.00	1418.00	20.00	1134.40
M COMPRESSOR ASSY X					1.00	74.00	20.00	59.20
M HORN ASSY-LOW PITCH X					1.00	1502.00	20.00	1201.60
M PANEL ASSY-HOOD / BT					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH / BT					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,LH / BT					1.00	430.00	20.00	344.00
M PANEL-FENDER,LH / BT					1.00	430.00	20.00	344.00
M PANEL-FENDER,RH / BT					1.00	497.00	20.00	397.60
M BEAM COMPLETE-FR BUMPER X					1.00	156.00	20.00	124.80
M PAD-HOOD INSULATING X					1.00	103.00	20.00	82.40
M LATCH ASSY-HOOD X					1.00	633.00	20.00	506.40
M COVER-FR BUMPER / BR					1.00	328.00	20.00	262.40
M GRILLE ASSY-RADIATOR / BR					1.00	485.00	20.00	388.00
M GRILLE-FRONT BUMPER					1.00	216.00	20.00	172.80
M MOULDING-FRONT BUMPER,RH / MIS					1.00	143.00	20.00	114.40
M LAMP ASSY-SIDE REPEATER,RH / CUT					1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11454/LAI ZHEN NAN (LI ZHENNAN) Reg No/Reg Date SMQ2932D*ECB1/ 07/11/201 Date In/Mileage 30/11/2020/ 0 Chassis No KNAF5416MK5052954 Engine No G4FGKH749533 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	30/11/2020/ 13:18	QUK	282 / Kevin Leong	25072			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	AIR DUCT-FR BUMPER,RH				1.00	14.00	20.00	11.20
M	STIFFNER-FR BPR LWR				1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE MTG			OK	1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG			OK	1.00	22.00	20.00	17.60
M	GUARD ASSY-FRONT WHEEL,RH				1.00	95.00	20.00	76.00
M	ORNAMENT-KIA NO.115				1.00	32.00	20.00	25.60
M	COVER ASSY-COWL TOP				1.00	247.00	20.00	197.60

Estimate

Steve (LKK) 00 - Not Author
EXCESS - ?
30/11/20, 3.00pm
P/P
10 dys
My Bel Jy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

- To confirm & accepted by "Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Authorized signatory and company stamp

Nett	14,787.60
7% GST on	1035.13
Total Payable	15,822.73

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.