



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013145/R1Kvf3e2	
			Date: 19/02/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBQ 6946T	Veh. Inspected	SHB 5309Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003477/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	30/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS 5DR HATCHBACK (AUTO)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTDKB3FU803089460	Colour	MAROON
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DUNLOP	5 mm
	L/H Front Tyre	195/65 R15	DUNLOP	5 mm
	R/H Rear Tyre	195/65 R15	DUNLOP	5 mm
	L/H Rear Tyre	195/65 R15	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/11/2020	Inspection Date	30/11/2020
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	