

TOTAL

Case Details

Case Reference Number : TAX/11/20/2058
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5309Y

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-13285-ID
 Assigned By : Tan Lee Ge #

Insurance Company Name : Sompoo Insurance Singapore Pte. Ltd
 Accident Date and Time : 26/11/2020 08:00 PM
 Vehicle Age(In Months) : 11

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	926.00	926.00	10.00	833.40	Replace	0	0	Not Give	▼
One Time Key In	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	1	206.70	206.70	25.00	155.02	Replace	0	0	Not Give	▼
One Time Key In	Main			CHANNEL SUB-ASSY, REAR DOOR GLASS , LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	▼
One Time Key In	Main			FILLER, REAR DOOR GLASS CHANNEL	1	14.90	14.90	25.00	11.18	Replace	0	0	Not Give	▼
One Time Key In	Main			GLASS SUB-ASSY, REAR DOOR, LH	1	410.90	410.90	25.00	308.17	Replace	0	0	Not Give	▼
One Time Key In	Main			PAD, FRONT SEAT BACK , LH	1	321.40	321.40	25.00	241.05	Replace	1	241.05	Replace	▼
One Time Key In	Main			COVER SUB-ASSY, FRONT SEAT BACK , LH	1	1,285.20	1,285.20	25.00	963.90	Replace	1	963.90	Replace	▼
One Time Key In	Main			COVER SUB-ASSY, FRONT SEAT CUSHION , LH	1	891.40	891.40	25.00	668.55	Replace	0	0	Not Give	▼
One Time Key In	Main			PAD, FRONT SEAT CUSHION , LH	1	489.90	489.90	25.00	367.42	Replace	0	0	Not Give	▼

Total Spare Part Cost	34,872.31	Surveyor Total	11,020.49
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	34,872.31	Final Sur Total	11,020.49

SMRT Recommendation												Surveyor Approval		
	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main		ADJUSTER ASSY, FRONT SEAT , LH	1	734.50	734.50	25.00	550.88	Replace	0	0	Not Give	✓	
One Time Key In	Main		ADJUSTER ASSY, FRONT SHOULDER SEAT BELT ANCHOR , RH & LH	1	126.50	126.50	25.00	94.88	Replace	0	0	Not Give	✓	
One Time Key In	Main		SEAT BELT ASSY, FRONT SEAT , LH	1	995.10	995.10	25.00	746.33	Replace	1	746.33	Replace	✓	
One Time Key In	Main		BUCKLE FRONT SEAT BELT ASSY, LH	1	177.00	177.00	25.00	132.75	Replace	0	0	Not Give	✓	
One Time Key In	Main		PLATE SUB-ASSY, FRONT SHOULDER SEAT BELT ANCHOR , LH	1	60.60	60.60	25.00	45.45	Replace	0	0	Not Give	✓	
One Time Key In	Main		SEAT BELT ASSY, FRONT SEAT , RH	1	995.10	995.10	25.00	746.33	Replace	1	746.33	Replace	✓	
One Time Key In	Main		BUCKLE FRONT SEAT BELT ASSY, RH	1	177.00	177.00	25.00	132.75	Replace	0	0	Not Give	✓	
One Time Key In	Main		PLATE SUB-ASSY, FRONT SHOULDER SEAT BELT ANCHOR , RH	1	60.60	60.60	25.00	45.45	Replace	0	0	Not Give	✓	
One Time Key In	Main		MOULDING, FRONT DOOR WINDOW FRAME , REAR LH	1	56.50	56.50	25.00	42.38	Replace	0	0	Not Give	✓	
One Time Key In	Main		MOULDING, REAR DOOR WINDOW FRAME , FRONT LH	1	56.50	56.50	25.00	42.38	Replace	0	0	Not Give	✓	
One Time Key In	Main		MOULDING, FRONT DOOR WINDOW FRAME , FRONT LH	1	38.60	38.60	25.00	28.95	Replace	0	0	Not Give	✓	
One Time Key In	Main		COVER SUB-ASSY, FRONT PILLAR , UPR LH	1	100.40	100.40	25.00	75.30	Replace	0	0	Check	✓	
One Time Key In	Main		MOULDING ASSY, FRONT DOOR BELT, LH	1	92.00	92.00	25.00	69.00	Replace	0	0	Check	✓	
One Time Key In	Main		MOULDING ASSY, REAR DOOR BELT, LH	1	113.50	113.50	25.00	85.13	Replace	0	0	Check	✓	

Total Spare Part Cost	34,872.31	Surveyor Total	11,020.49
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	34,872.31	Final Sur Total	11,020.49

Sp Reading 53547
of 1008, BUKIT MELAK 203 H01-04

Line Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Approval			Remarks
					List Price Per Unit(\$)	List Price(\$)						Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main		MOULDING, FRONT DOOR WINDOW FRAME, UPPER LH	1	92.00	92.00		25.00	69.00	Replace	0	0		Check	▼
One Time Key In	Main		MOULDING, REAR DOOR WINDOW FRAME, REAR LH	1	38.60	38.60		25.00	28.95	Replace	0	0		Check	▼
One Time Key In	Main		COVER SUB-ASSY, REAR QUARTER PILLAR, LH	1	207.30	207.30		25.00	155.48	Replace	0	0		Check	▼
One Time Key In	Main		MOULDING ASSY, BODY ROCKER PANEL, LH	1	594.80	594.80		25.00	446.10	Replace	1	446.10		Replace	▼
One Time Key In	Main		PANEL SUB-ASSY, FENDER REAR LH	1	871.50	871.50		25.00	653.63	Replace	1	653.63		Replace	▼
One Time Key In	Main		PATCH, SIDE PANEL REAR END, RH & LH	1	33.70	33.70		25.00	25.28	Replace	0	0		Not Give	▼
One Time Key In	Main		LINER, REAR FENDER, LH	1	139.80	139.80		25.00	104.85	Replace	0	0		Check	▼
One Time Key In	Main		WHEEL, DISC	1	1,879.40	1,879.40		25.00	1,409.55	Replace	1	0		Repair	▼
One Time Key In	Main		TYRE	1	126.74	126.74		0.00	126.74	Replace	0	0		Not Give	▼
One Time Key In	Main		REAR BUMPER REINFORCEMENT	1	332.70	332.70		25.00	249.52	Replace	0	0		Not Give	▼
One Time Key In	Main		COVER, RR BUMPER ASSY	1	485.60	485.60		25.00	364.20	Replace	1	0		Repair	▼
One Time Key In	Main		PAD, RR BUMPER, RH & LH, 3	1	11.00	11.00		25.00	8.25	Replace	0	0		Not Give	▼
One Time Key In	Main		PAD, RR BUMPER, RH & LH, 2	1	4.00	4.00		25.00	3.00	Replace	0	0		Not Give	▼
One Time Key In	Main		PAD, RR BUMPER, RH & LH, 1	1	4.00	4.00		25.00	3.00	Replace	0	0		Not Give	▼
One Time Key In	Main		PAD, RR BUMPER, CTR	3	11.00	33.00		25.00	24.75	Replace	0	0		Not Give	▼

Total Spare Part Cost	34,872.31	Surveyor Total	11,020.49
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	34,872.31	Final Sur Total	11,020.49

SMRT Recommendation										Surveyor Approval			
Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In		RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	✓	
One Time Key In		RETAINER, RR BUMPER, LH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	✓	
One Time Key In		CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	0	0	Not Give	✓	
One Time Key In		COVER, REAR FLOOR UNDER , LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give	✓	
One Time Key In		HUB & BEARING ASSY, RH & LH	1	668.90	668.90	25.00	501.67	Replace	0	0	Not Give	✓	
One Time Key In		MIRROR ASSY, OUTER REAR VIEW , LH	1	1,339.30	1,339.30	10.00	1,205.37	Replace	0	0	Not Give	✓	
One Time Key In		COVER, OUTER MIRROR, LH	1	108.60	108.60	25.00	81.45	Replace	1	0	Repair	✓	
One Time Key In		MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	1	54.40	54.40	25.00	40.80	Replace	0	0	Check	✓	
One Time Key In		MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	1	54.40	54.40	25.00	40.80	Replace	0	0	Check	✓	
One Time Key In		MOULDING SUB-ASSY, ROOF TOP	1	656.90	656.90	25.00	492.67	Replace	0	0	Check	✓	
One Time Key In		TAILGATE TRIM , UPPER	1	52.10	52.10	25.00	39.08	Replace	0	0	Not Give	✓	
One Time Key In		TAILGATE TRIM , RH	1	95.60	95.60	25.00	71.70	Replace	0	0	Not Give	✓	
One Time Key In		TAILGATE TRIM , LH	1	95.60	95.60	25.00	71.70	Replace	0	0	Not Give	✓	
One Time Key In		TAILGATE TRIM , LOWER	1	225.20	225.20	25.00	168.90	Replace	0	0	Not Give	✓	
One Time Key In		TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	28.90	28.90	25.00	21.67	Replace	0	0	Check	✓	

Total Spare Part Cost 34,872.31

Surveyor Total 11,020.49

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 34,872.31

Final Sur Total 11,020.49

SMRT Recommendation

Surveyor Approval

Portion	Material Number	Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In		TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,656.70	1,656.70	25.00	1,242.53	Replace	0	0	Check	▼
One Time Key In		PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	▼
One Time Key In		SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Check	▼
One Time Key In		WIRE, FRONT DOOR, LH	1	474.80	474.80	10.00	427.32	Replace	0	0	Check	▼
One Time Key In		WIRE, REAR DOOR, LH	1	247.40	247.40	10.00	222.66	Replace	0	0	Check	▼
One Time Key In		AIR BAG ASSY, ROOF SIDE CURTAIN SHIELD, LH	1	1,748.10	1,748.10	10.00	1,573.29	Replace	1	1,573.29	Replace	▼
One Time Key In		AIR BAG ASSY, FRONT SEAT, LH	1	1,008.80	1,008.80	10.00	907.92	Replace	1	907.92	Replace	▼
One Time Key In		SENSOR, AIR BAG, FRONT, RH & LH	1	373.90	373.90	10.00	336.51	Replace	1	336.51	Replace	▼
One Time Key In		AIR BAG, COMPUTER ASSY	1	1,546.00	1,546.00	10.00	1,391.40	Replace	0	0	Check	▼
One Time Key In		SENSOR, SIDE AIR BAG, RH & LH, NO.2	1	709.30	709.30	10.00	638.37	Replace	0	0	Check	▼
One Time Key In		SENSOR, DOOR SIDE AIR BAG PRESSURE, RH & LH	1	379.20	379.20	10.00	341.28	Replace	0	0	Check	▼
One Time Key In		SENSOR, SIDE AIR BAG REAR, RH & LH	1	567.80	567.80	10.00	511.02	Replace	0	0	Check	▼
One Time Key In		PROTECTOR, SEAT SLIDE POSITION SENSOR	1	23.10	23.10	25.00	17.33	Replace	0	0	Check	▼
One Time Key In		ADJUSTER ASSY, FRONT SEAT, LH	1	734.50	734.50	10.00	661.05	Replace	0	0	Not Give	▼
One Time Key In		PANEL, ROOF	1	1,283.90	1,283.90	25.00	962.93	Replace	0	0	Check	▼

Total Spare Part Cost 34,872.31

Surveyor Total 11,020.49

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 34,872.31

Final Sur Total 11,020.49

SMRT Recommendation										Surveyor Approval			
Line Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main		ROOF HEADLINING ASSY	1	2,125.70	2,125.70	25.00	1,594.27	Replace	1	1,594.	Replace	▼
One Time Key In	Main		PAD, ROOF SILENCER , NO.1	1	102.80	102.80	25.00	77.10	Replace	0	0	Not Give	▼
One Time Key In	Main		PAD, ROOF SILENCER , NO.2	1	146.40	146.40	25.00	109.80	Replace	0	0	Not Give	▼
One Time Key In	Main		PILLAR, FRONT BODY, LH	1	350.00	350.00	25.00	262.50	Replace	0	0	Not Give	▼
One Time Key In	Main		BRACKET, FRONT FENDER MOUNTING , RH & LH	1	9.50	9.50	25.00	7.13	Replace	0	0	Not Give	▼
One Time Key In	Main		PILLAR, CENTER BODY, OUTER LH	1	323.10	323.10	25.00	242.33	Replace	1	0	Repair	▼
One Time Key In	Main		MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	288.50	288.50	25.00	216.38	Replace	1	0	Repair	▼
One Time Key In	Main		REINFORCEMENT SUB-ASSY , CENTER BODY PILLAR , LH	1	662.90	662.90	25.00	497.17	Replace	0	0	Check	▼
One Time Key In	Main		REINFORCEMENT SUB-ASSY, ROCKER PANEL , LH	1	343.40	343.40	25.00	257.55	Replace	0	0	Check	▼
One Time Key In	Main		REINFORCEMENT SUB-ASSY FRONT PILLAR , LOWER LH	1	545.80	545.80	25.00	409.35	Replace	0	0	Not Give	▼
One Time Key In	Main		PANEL SUB-ASSY, FRONT DOOR LH	1	1,300.70	1,300.70	25.00	975.53	Replace	1	975.53	Replace	▼
One Time Key In	Main		STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	▼
One Time Key In	Main		CHECK ASSY, FRONT DOOR	1	183.80	183.80	25.00	137.85	Replace	0	0	Check	▼
One Time Key In	Main		WEATHERSTRIP, FRONT DOOR LH	1	231.30	231.30	25.00	173.48	Replace	0	0	Check	▼
One Time Key In	Main		GLASS SUB-ASSY, FRONT DOOR , LH	1	522.00	522.00	25.00	391.50	Replace	1	391.50	Replace	▼

Total Spare Part Cost 34,872.31

Surveyor Total 11,020.49

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 34,872.31

Final Sur Total 11,020.49

SMRT Recommendation

Surveyor Approval

Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main	MOULDING, FRONT DOOR WINDOW FRAME , REAR LH	1	56.50	56.50	25.00	42.38	Replace	0	0	Check	▼
One Time Key In	Main	COVER, FRONT DOOR SERVICE HOLE , LH	1	23.90	23.90	25.00	17.92	Replace	0	0	Check	▼
One Time Key In	Main	PROTECTOR, FRONT DOOR PANEL , LH	1	50.70	50.70	25.00	38.03	Replace	0	0	Check	▼
One Time Key In	Main	SEAL, FRONT DOOR VENT, LH	1	17.30	17.30	25.00	12.98	Replace	0	0	Check	▼
One Time Key In	Main	COVER, FRONT DOOR SERVICE HOLE , LH	1	188.10	188.10	25.00	141.07	Replace	0	0	Check	▼
One Time Key In	Main	GLASS, FRONT DOOR FIX WINDOW , LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	▼
One Time Key In	Main	WEATHERSTRIP, FRONT DOOR FIX WINDOW , LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	▼
One Time Key In	Main	FRAME SUB-ASSY, FRONT DOOR , FRONT LOWER LH	1	144.60	144.60	25.00	108.45	Replace	0	0	Check	▼
One Time Key In	Main	RUN, FRONT DOOR GLASS , LH	1	153.60	153.60	25.00	115.20	Replace	0	0	Check	▼
One Time Key In	Main	FRAME SUB-ASSY, FRONT DOOR , REAR LOWER LH	1	88.50	88.50	25.00	66.38	Replace	0	0	Check	▼
One Time Key In	Main	GARNISH, DOOR FRAME, RH	1	13.10	13.10	25.00	9.82	Replace	0	0	Not Give	▼
One Time Key In	Main	GARNISH, DOOR FRAME, LH	1	13.10	13.10	25.00	9.82	Replace	0	0	Not Give	▼
One Time Key In	Main	WEATHERSTRIP, FR LH	1	138.00	138.00	25.00	103.50	Replace	0	0	Check	▼
One Time Key In	Main	PANEL ASSY, FR DOOR TRIM BOARD LH	1	746.50	746.50	25.00	559.88	Replace	0	0	Check	▼
One Time Key In	Main	ARMREST ASSY, FR LH	1	143.40	143.40	25.00	107.55	Replace	0	0	Check	▼

Total Spare Part Cost 34,872.31

Lump Sum Discount (%) 0.00

Final Spare Part Cost 34,872.31

Surveyor Total 11,020.49

Lump Sum Dis (%) 0

Final Sur Total 11,020.49

Sb Reading

of 1008, BUKIT MERAH L23 H01-04

SMRT Recommendation												Surveyor Approval			Remarks
Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace				
One Time Key In	Main	PANEL, FRONT ARMREST BASE, UPPER LH	1	50.80	50.80	25.00	38.10	Replace	0	0	Not Give	▼			
One Time Key In	Main	LOCK ASSY, FRONT DOOR LH	1	561.90	561.90	25.00	421.42	Replace	0	0	Check	▼			
One Time Key In	Main	DOOR LOCK STRIKER	1	39.30	39.30	25.00	29.47	Replace	0	0	Not Give	▼			
One Time Key In	Main	DOOR OUTER HANDLE FRONT , LH	1	390.60	390.60	25.00	292.95	Replace	1	292.95	Replace	▼			
One Time Key In	Main	DOOR FRONT , COVER OUTER HANDLE , LH	1	17.90	17.90	25.00	13.42	Replace	0	0	Check	▼			
One Time Key In	Main	DOOR PAD REAR , FRT & RR DOOR OUTER HANDLE , RH & LH	1	16.40	16.40	25.00	12.30	Replace	0	0	Check	▼			
One Time Key In	Main	DOOR PAD FRONT , FRT & RR DOOR OUTER HANDLE , RH & LH	1	16.40	16.40	25.00	12.30	Replace	0	0	Check	▼			
One Time Key In	Main	DOOR FRAME INNER HANDLE FRONT , LH	1	193.50	193.50	25.00	145.13	Replace	0	0	Check	▼			
One Time Key In	Main	DOOR FRONT ROD, LOCK OPEN , LH	1	19.50	19.50	25.00	14.63	Replace	0	0	Check	▼			
One Time Key In	Main	HINGE ASSY, FRONT DOOR , UPPER LH	1	97.50	97.50	25.00	73.13	Replace	0	0	Check	▼			
One Time Key In	Main	HINGE ASSY, FRONT DOOR , LOWER LH	1	110.60	110.60	25.00	82.95	Replace	0	0	Check	▼			
One Time Key In	Main	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	1	238.30	238.30	25.00	178.73	Replace	0	0	Check	▼			
One Time Key In	Main	DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	926.00	926.00	10.00	833.40	Replace	0	0	Check	▼			
One Time Key In	Main	PANEL SUB-ASSY, REAR DOOR , LH	1	1,294.90	1,294.90	25.00	971.18	Replace	1	971.18	Replace	▼			
One Time Key In	Main	CHECK ASSY, REAR DOOR	1	183.80	183.80	25.00	137.85	Replace	0	0	Check	▼			

Total Spare Part Cost 34,872.31
 Lump Sum Discount (%) 0.00
 Final Spare Part Cost 34,872.31

Surveyor Total 11,020.49
 Lump Sum Dis (%) 0
 Final Sur Total 11,020.49

		SMRT Recommendation										Surveyor Approval			
	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks		
One Time Key In	Main		WEATHERSTRIP, REAR DOOR LH	1	180.10	180.10	25.00	135.07	Replace	0	0	Check	▼		
One Time Key In	Main		CUSHION REAR DOOR PANEL	1	5.50	5.50	25.00	4.13	Replace	0	0	Not Give	▼		
One Time Key In	Main		PAD, FRONT AND REAR DOOR SILENCER	1	34.10	34.10	25.00	25.58	Replace	0	0	Check	▼		
One Time Key In	Main		COVER, REAR DOOR SERVICE HOLE , NO.2 , LH	1	21.10	21.10	25.00	15.83	Replace	0	0	Check	▼		
One Time Key In	Main		PROTECTOR, REAR DOOR PANEL , LH	1	8.40	8.40	25.00	6.30	Replace	0	0	Not Give	▼		
One Time Key In	Main		SEAL, REAR DOOR VENT, LH	1	16.30	16.30	25.00	12.23	Replace	0	0	Not Give	▼		
One Time Key In	Main		GLASS SUB-ASSY, REAR DOOR, LH	1	410.90	410.90	25.00	308.17	Replace	1	0	Repair	▼		
One Time Key In	Main		GLASS , REAR DOOR QUARTER WINDOW , LH	1	108.10	108.10	25.00	81.07	Replace	0	0	Not Give	▼		
One Time Key In	Main		WEATHERSTRIP, REAR DOOR QUARTER WINDOW , LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	▼		
One Time Key In	Main		RUN, REAR DOOR GLASS , LH	1	122.50	122.50	25.00	91.88	Replace	0	0	Check	▼		
One Time Key In	Main		WEATHERSTRIP, REAR DOOR GLASS, INNER LH	1	103.20	103.20	25.00	77.40	Replace	0	0	Check	▼		
One Time Key In	Main		BOARD SUB-ASSY, REAR DOOR TRIM, LH	1	566.60	566.60	25.00	424.95	Replace	0	0	Check	▼		
One Time Key In	Main		DOOR OUTER HANDLE REAR , LH	1	97.40	97.40	25.00	73.05	Replace	1	0	Repair	▼		
One Time Key In	Main		DOOR PAD FRONT , FRT & RR DOOR OUTER HANDLE , RH & LH	1	16.40	16.40	25.00	12.30	Replace	0	0	Check	▼		
One Time Key In	Main		DOOR PAD REAR , FRT & RR DOOR OUTER HANDLE , RH & LH	1	16.40	16.40	25.00	12.30	Replace	0	0	Check	▼		
Total Spare Part Cost								34,872.31							
Lump Sum Discount (%)								0.00							
Final Spare Part Cost								34,872.31							
											Surveyor Total	11,020.49			
											Lump Sum Dis (%)	0			
											Final Sur Total	11,020.49			

SMRT Recommendation										Surveyor Approval			
Line No	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main		DOOR REAR , COVER OUTER HANDLE , RH & LH	1	17.90	17.90	25.00	13.42	Replace	0	0	Not Give	✓
One Time Key In	Main		DOOR FRAME INNER HANDLE REAR , LH	1	193.50	193.50	25.00	145.13	Replace	0	0	Not Give	✓
One Time Key In	Main		DOOR LOCK REAR , LH	1	561.90	561.90	25.00	421.42	Replace	0	0	Check	✓
One Time Key In	Main		DOOR LOCK STRIKER	1	39.30	39.30	25.00	29.47	Replace	0	0	Not Give	✓
One Time Key In	Main		HINGE ASSY, REAR DOOR , UPPER LH	1	98.90	98.90	25.00	74.18	Replace	0	0	Not Give	✓
One Time Key In	Main		HINGE ASSY, REAR DOOR , LOWER LH	1	87.10	87.10	25.00	65.32	Replace	0	0	Not Give	✓
Total Spare Part Cost								34,872.31	Surveyor Total 11,020.49				
Lump Sum Discount (%)								0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost								34,872.31	Final Sur Total 11,020.49				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	1,183.00	900	
Total:			1,183.00	900.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	RESPRAY MIRROR COVER LH	180.00	60	
2	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
3	Main	TO REPSRAY REAR DOOR LH	378.00	200	
4	Main	TO RESPRAY REAR FENDER LH	378.00	200	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	80	
6	Main	TO RESPRAY RIM	180.00	50	
Total:			3,330.00	1,120.00	

	Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
		TO RESPRAY REAR BUMPER	378.00	200	
8	Main	TO RESPRAY BUMPER BEAM	180.00	0	
9	Main	TO RESPRAY FRONT PILLAR LH	180.00	0	
10	Main	TO RESPRAY CENTER PILLAR LH	180.00	80	
11	Main	TO RESPRAY REAR PILLAR LH	180.00	0	
12	Main	TO RESPRAY LH RAIL ROOF SIDE	180.00	50	
13	Main	TO RESPRAY ROOF TOP PANEL	378.00	0	
Total:			3,330.00	1,120.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	50	
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
3	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
4	Main	TO TRANSFER DOOR MECHANISM	240.00	100	
5	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	350.00	125	
7	Main	TO SUPPLY SOLAR FILM (SIDE WINDOW GLASS)	480.00	0	
8	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40	
9	Main	TO CHECK AND RESET CNG SYSTEM	80.00	0	
10	Main	TO REMOVE AND REFIX AIR BAG SYSTEM	120.00	80	
11	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0	
12	Main	TOWING CHARGE	56.00	40	
13	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			2,166.00	435.00	

Job Scope

TO WASH AND VACUUM

SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
60.00	0	
2,166.00	435.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	34,872.31	11,020.49
Total Labour Cost	1,183.00	900.00
Total Spray Painting	3,330.00	1,120.00
Other	2,166.00	435.00
Overall Total	41,551.31	13,475.49
Lump Sum Repair Option		☐
Lump Sum Total	0.00	13,475.49
Surveyor Approved Amount		13,475.49
No of Repair Days*	10	8
Remarks		

part by part repair / before paint photo/ FOR CHECK ITEM
and REPLACE ITEM PLEASE CALL SURVEYOR RASUL
/ HP : 0001 0000 email: rasul@lkkauto.com

Surveyor Name

Rasul

Signature

Rasul

Save Clear

Survey Date

30/11/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT:

Date Of Report	27/11/2020 08:00
Date Of Accident	27/11/2020 04:00
Exact Location Of Accident	JUNCTION OF GUILLEMARD ROAD AND LOR 22 GEYLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE:

Vehicle Registration Number	SHB5309Y
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	TARC@SMRT.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095484MFSH
Cover Note Number	

Driver

Name of Driver	SHIM AIK TIAN
NRIC No	SXXXX738J
Date Of Birth	26/06/1960
Occupation	OUTDOOR
Date Of Driving Pass	27/12/1978
Driving Experience	41 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Is the Driver an employee of the Insured's Company? NO
 Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: SD CARD WITH TRAFFIC POLICE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBQ6946T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

UNKNOWN RIDER

imate Age
ies Sustain
injured person in which vehicle?

FBQ6946T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?


YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
MORPHOLOGY

CONFIDENTIAL

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing my claim, settling or/and making claims including the settlement of my claims and any other matter relating to the claim;

(ii) for all other legal and/or regulatory obligations;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) for the purpose of my claim, including the mailing of correspondence, statements of incident, reports of accident, etc., which could involve disclosure of certain personal data about me to bring about delivery of the same as well as my claim and/or other services/packages provided;

(v) for all other legal and/or regulatory obligations, including the settlement of my claims and any other matter relating to the claim.

I understand that the Insurers, my workshop and the GIA may/are permitted to use my Personal Information for the purpose(s) of:

(i) for the purpose of my claim, including the mailing of correspondence, statements of incident, reports of accident, etc., which could involve disclosure of certain personal data about me to bring about delivery of the same as well as my claim and/or other services/packages provided;

(ii) for all other legal and/or regulatory obligations, including the settlement of my claims and any other matter relating to the claim.

I understand that the Insurers, my workshop and the GIA may/are permitted to use my Personal Information for the purpose(s) of:

(i) for the purpose of my claim, including the mailing of correspondence, statements of incident, reports of accident, etc., which could involve disclosure of certain personal data about me to bring about delivery of the same as well as my claim and/or other services/packages provided;

(ii) for all other legal and/or regulatory obligations, including the settlement of my claims and any other matter relating to the claim.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MSR 120105457 Vehicle Registration No: SHB 5309Y

Name (as shown in NRIC) : SMRT TAXIS PTE LTD NRIC/FIN/Passport No : 19J905369K

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore()

Contact (Tel) : _____ Mobile No. : _____

Email Address : TARC@smrt.com.sg

Date of Accident : 27/11/2020 Time of Accident : 0400 HRS

Place of Accident : JUNCTION OF GUILLEMARD RD & LOR 22 SEYLANG

Insurance Company : MS FIRST CAPITAL INSURANCE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TO ATTACHED POLICE REPORT

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

SINGAPORE POLICE FORCE



T/20201127/2023

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20201127/2023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/11/2020 10:55	Vide Report No.: G/20201127/0036	Station Diary No.: 36
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: SHIM AIK TIAN			Address: APT BLK 109 YISHUN RING ROAD #09-339 SINGAPORE 760109	
ID Type / ID No.: NRIC NO / S1456738J			Contact No.: Home/Office: Mobile: 98473241	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 60	Date of Birth: 26/06/1960	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 27/11/2020 04:00	Type of Location: T-Junction
Location: GUILLEMARD ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBQ6946T	Motorcycle				Seriously Damaged	0
SHB6946T	Taxi				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20201127/2023

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3

Report No. T/20201127/2023

CONTINUATION OF REPORT

Driver				
Name	SHIM AIK TIAN		ID No.	S1456738J
Related Vehicle	NIL		Contact No.	98473241
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 27 November 2020 at about 4am, my taxi bearing the registration number SHB5309Y was involved with motorbike bearing the registration number FBQ6946T. The accident happened at the "T" Junction of Guillemard Road leading to Geylang Lorong 22.

The traffic light arrow shows that I am allowed to turn right to Geylang Lorong 22. Halfway through to turning right, the motorbike rode straight ahead and hit into the left side of my taxi.

I was not injured. But the motorcyclist got injured. I did not manage to exchange particulars with the motorcyclist. The police and ambulance came and the motorcyclist was conveyed to the hospital.

I am making this report as the motorcyclist was injured.

**SINGAPORE
POLICE FORCE**



T/20201127/2023

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20201127/2023

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

ASP MOHAMAD HAZIQ BIN MOHAMAD
IKHSAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt SYED MUHAMMAD ISA BIN OMAR
ALHABSHEE

Contact No.: 65476214

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

27/11/2020 10:55

Classification Of Case: