


CS/CTI20013146/Assignment

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SY 5883 D Yr Regn: Dec / 2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hissan Qashqai C.O. 1197
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 108683 T/Radio: Insured / Std / NI / NA
 Eng/No: HRA 2211199A
 C/No: SNHFEA511U1533447
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / SRM / STD A/Rm or
 Tyre Size: F: 215/60 R17
 R: — " —

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Bridgestone

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 2/11/22 D.O.A. 30/11/22
 Survey held at JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>China Teiping GBK 5795D</u>
<u>29/12/2020</u>	<u>Insured 2 (\$14,500/-) with 10 days 7 in</u> <u>(\$27,098.47 Red - 65%)</u>

Date/Time, File Pass to?

29/12/20

1)

Typ. 4

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S+RS \$

Photo

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / L.B.: (\$ 14,500/- 4/5)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/12/2020 13:50 (SGT)
Date of Accident	27/11/2020 12:05 (SGT)
Exact Location of Accident	48A Berwick Dr, Singapore 559928
Additional Location Information	BERWICK DRIVE TOWARDS TAVISTOCK AVENUE JUNCTION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SY5883D
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN SECK YONG
NRIC No	SXXXX189E
Email Address	syneltan@yahoo.com.sg
Mobile Phone No	(Phone) +65-97980089
Alternative Phone No	+65-97980089

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Qashqai
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5076025472-04
Cover Note Number	-

DRIVER

Name of Driver	TAN SECK YONG
NRIC No	SXXXX189E
Date Of Birth	26/12/1961
Occupation	Outdoor

Date Of Driving Pass	25/06/1979
Driving experience	41 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97980089
Alt. Phone Number	+65-97980089
Email Address	syneltan@yahoo.com.sg
Address	BLK 152 #36-328 LORONG 2 TOA PAYOH
Address complement	-
Postcode	310152
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED;


ATTACHMENT(S)


Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (YAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415853
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NIC/PIN No.: 28 NOV 2020

SKETCH PLAN #2

SKETCH PLAN

Bennick Dr towards
Tavistock Ave Junction

Vehicle A: SY5883D
Vehicle B: G8K5795A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle A (5YB03D) was travelling straight along the stated location. Suddenly, vehicle B (ABK579SA) came out from right side without stopping and collided onto my front right portion of my vehicle causing damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

SDAG KAKI BUKIT (PAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415935
Tel: 67416697 Fax: 67492505
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 28 NOV 2020

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBK5795A [YOUR INSURED] & SY5883D [OUR CLIENT]
ON 27/11/2020.

ESTIMATED REPAIR COSTS FOR SY5883D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET <i>Demol</i>	961.40	\$ 1,261.40 ✓
1PC	BONNET INSULATOR <i>bt changed</i>		\$ 290.40 ✓
1PC	BONNET LOCK <i>bt</i>		\$ 199.80 ✓
2PCS	BONNET HINGE LH / RH @ \$78.20 EACH <i>bt</i>		\$ 156.40 ✓
1PC	BONNET STRIKER LOCK <i>bt</i>		\$ 93.20 ✓
1PC	BONNET SEAL <i>svc</i>		\$ 98.00 X
1SET	BONNET STOPPERS <i>svc</i>	6 12.20 x 2 = 122.40	\$ 59.90 X
2PCS	HEAD LAMP LH / RH @ \$959.00 EACH <i>o/s broken n/s ok mndy</i>		\$ 1,918.00 ✓
2PCS	HEAD LAMP LOWER BRACKET LH / RH @ \$141.60 EACH <i>mt</i>		\$ 283.20 X
2PCS	HEAD LAMP PANEL LH / RH @ \$209.30 EACH <i>ns</i>		\$ 418.60 X
1PC	HEAD LAMP WIRE HARNESS <i>svc</i>		\$ 1,854.00 X
1PC	FRONT BUMPER <i>cut Demol</i>	717.00	\$ 1,014.50 ✓
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$60.90 EACH <i>o/s broken</i>		\$ 121.80 ✓
2PCS	FRONT BUMPER FOG LAMP LH / RH @ \$421.60 EACH <i>o/s broken n/s mt</i>		\$ 843.20 ✓
2PCS	FRONT BUMPER FOG LAMP GARNISH LH / RH @ \$215.50 EACH <i>o/s damaged n/s mt</i>		\$ 431.00 ✓
2PCS	FRONT BUMPER FOG LAMP HOLDER LH / RH @ \$195.20 EACH <i>ns</i>		\$ 390.40 X
1PC	FRONT BUMPER FOG LAMP WIRE HARNESS <i>svc</i>		\$ 1,838.90 X
1PC	FRONT BUMPER TOW HOOK COVER <i>mt</i>		\$ 40.30 X
1PC	FRONT BUMPER GRILLE <i>avale broken</i>		\$ 598.30 ✓
1PC	FRONT REINFORCEMENT BAR UPPER <i>Demol</i>	675.40	\$ 875.40 ✓
1PC	FRONT REINFORCEMENT BAR LOWER <i>mt</i>		\$ 537.70 X
1PC	HORN <i>cut broken</i>		\$ 153.00 ✓
1PC	FRONT SUPPORT PANEL <i>bt Demol</i>	792.50	\$ 917.50 ✓
1PC	INTER COOLER ASSY <i>bt Demol</i>	1850.30	\$ 2,121.00 ✓
1PC	WIPER WASHER TANK <i>broken mndy</i>		\$ 348.40 ✓
1PC	WIPER WASHER TANK MOTOR <i>mt</i>		\$ 148.10 X
1PC	WIPER WASHER TANK HOSE <i>mt</i>		\$ 138.90 X
1PC	A/C CONDENSOR ASSY <i>bt</i>	1498.80	\$ 1,498.80 ✓
1PC	A/C CONDENSOR FAN COMPLETE <i>mt</i>		\$ 621.70 X
1PC	A/C CONDENSOR LOW PRESSURE PIPE <i>mt</i>		\$ 425.90 X

1PC	A/C CONDENSOR HIGH PRESSURE PIPE HH	\$ 337.40	X
1PC	A/C CONDENSOR DISCHARGE PIPE HH	\$ 337.40	X
1PC	RADIATOR ASSY <i>Punctured / mainly broken</i> 1387.40	\$ 1,387.40	✓
1PC	RADIATOR TOP HOSE HH	\$ 103.60	X
1PC	RADIATOR BOTTOM HOSE HH	\$ 185.30	X
1PC	RADIATOR FAN MOTOR HH	\$ 332.80	X
1PC	RADIATOR FAN BLADE HH	\$ 195.90	X
1PC	RADIATOR FAN COWLING HH	\$ 395.20	X
2PCS	FRONT FENDER LH / RH @ \$822.70 EACH <i>Distorted 622.70 x 2 = 1245.40</i>	\$ 1,645.40	✓
2PCS	FRONT FENDER ARC GARNISH LH / RH @ \$483.00 EACH <i>wt / broken</i>	\$ 966.00	✓
2PCS	FRONT FENDER INNER SHIELD LH / RH @ \$153.50 EACH <i>ops torn</i>	\$ 307.00	✓
1PC	FRONT WHEEL HOUSING RH <i>Distorted</i> 812.30 <i>1/5 HH</i>	\$ 1,094.40	✓
1PC	FRONT WHEEL BEARING & HUB ASSY RH HH	\$ 432.30	X
1PC	FRONT ABSORBER RH HH	\$ 647.50	X
1PC	FRONT LOWER ARM RH <i>distorted</i> 349.60	\$ 440.50	✓
1PC	FRONT KNUCKLE ARM RH <i>distorted</i> 583.20	\$ 683.20	✓
1PC	FRONT STABILIZER BAR HH	\$ 503.30	X
1PC	FRONT STABILIZER LINK RH HH	\$ 140.80	X
1PC	FRONT TIE ROD RH HH	\$ 192.00	X
1PC	FRONT TIE ROD END RH HH	\$ 121.00	X
1PC	FRONT DOOR RH <i>key</i>	\$ 1,104.80	X
1PC	FRONT DOOR BLACK PLASTIC RH HH	\$ 175.40	X
1PC	FRONT DOOR WINDOW MOULDING RH HH	\$ 120.70	X
1PC	FRONT DOOR CHROME MOULDING RH HH	\$ 188.90	X
1PC	A PILLAR RH HH	\$ 1,530.30	X
1PC	FRONT WINDSCREEN HH	\$ 1,244.60	X
1PC	FRONT WINDSCREEN MOULDING HH	\$ 234.60	X
1PC	FRONT WINDSCREEN LOWER GARNISH HH	\$ 244.90	X
1PC	RADIATOR RESERVE TANK <i>broken</i> 268.10	\$ 268.10	✓

16022.80
14420.52

PARTS SUM: \$ 34,991.00
PARTS LESS 10%: \$ 3,499.10
PARTS TOTAL: \$ 31,491.90

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY BONNET INNER TRIM CLIPS <i>HH Nec</i>	\$ 50.00	15/-
*	TO SUPPLY HEAD LAMP CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT GRILLE CLIPS <i>Nec</i>	\$ 50.00	15/-
*	TO SUPPLY FRONT BUMPER CLIPS <i>Nec</i>	\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER GRILLE CLIPS <i>Use separator</i>	\$ 50.00	15/- X
*	TO SUPPLY FRONT BUMPER UNDER COVER CLIPS HH	\$ 50.00	X
*	TO SUPPLY COOLANT <i>Nec (Leaked)</i>	\$ 100.00	40/-
*	TO SUPPLY FRONT WINDSCREEN SEALANT HH	\$ 80.00	X
*	TO SUPPLY FRONT WINDSCREEN DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY FRONT WHEEL HOUSING SEALANT <i>Nec</i>	\$ 80.00	40/-

*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS o/s 460	\$ 50.00 15/-
*	TO SUPPLY FRONT NO. PLATE & CASING 1/4	\$ 100.00 45/-
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 120/- 1/4
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00 1200/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00 1000/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 40/-
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$ 200.00 120/-
*	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	\$ 200.00 50/-
*	TO RNR FRONT INTER-COOLER TO FACILITATE REPAIRS	\$ 200.00 50/-
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00 1/4 150/-
*	TO CONDUCT COMPUTERIZE 4 WHEEL ALIGNMENT	\$ 150.00 60/-
*	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	\$ 500.00 1/4
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 300.00 30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 150/-

LABOUR & S/N TOTAL: \$ 8,390.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 39,881.90

41,598.47

30/11/2020 @ 1730hrs

N/A Actual

2/5mm 10 days.

Man

LKK Auto

Signature

Check part prices.

17460.52

Supp 690.57

18151.09

4/5 14500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBK5795A [YOUR INSURED] & SY5883D [OUR CLIENT]
ON 27/11/2020.

SUPPLYMENTARY ITEMS FOR SY5883D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
		161.20
1PC	AIR INTAKE DUCT <i>broken</i> 208.00	\$ 495.80 ✓
1PC	A/C CONDENSOR SIDE GARNISH LH / RH @ \$285.70 EACH <i>broken</i>	\$ 571.40 ✓
1PC	A/C CONDENSOR TOP GARNISH <i>broken</i> 454.40	\$ 529.40 ✓
		398.10
	PARTS SUM: \$	1,596.60
	PARTS LESS 10%: \$	159.66
	PARTS TOTAL: \$	1,436.94
	GRAND TOTAL SUPPLEMENTARY ITEMS: \$	1,436.94

1 ym

2kk Ando

8

767.30

1073 690.57

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SY 5883 D

Technician:

Mileage:

Time Printed 1.12.20 10:22 AM

NISSAN QASHQAI

Front : Left

Actual	BEFORE	Specified Range
-0°33'		-1°05' 0°25'
5°24'		1°50' 3°20'
-0°13'		-0°01' 0°03'
16°09'		13°35' 15°05'
15°36'		12°30' 15°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
5°17'		-1°05' 0°25'
5°20'		1°50' 3°20'
-3°19'		-0°01' 0°03'
5°18'		13°35' 15°05'
10°35'		12°30' 15°30'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-5°50'		
0°03'		
10°51'		
-3°32'		-0°02' 0°07'

Rear : Left

Actual	BEFORE	Specified Range
-1°25'		-1°14' -0°14'
-0°28'		0°03' 0°11'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°42'		-1°14' -0°14'
0°33'		0°03' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	BEFORE	Specified Range
0°17'		
0°05'		0°06' 0°23'
-0°31'		
0mm		