

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 30.11.20

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SLJ3947D
MODEL : TOYOTA COROLLA ALTIS
DATE OF ACCIDENT : 29.11.20
TIME OF ACCIDENT : 10:25HRS

Veron.

MROS3RE H104361961

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER RH <i>Dented</i>	1	\$ 781.20	\$ 781.20
2	FRONT FENDER EMBLEM (VVTI) RH <i>New</i>	1	\$ 38.90	\$ 38.90
3	FRONT FENDER INNER COWLING RH <i>cut</i>	1	\$ 199.20	\$ 199.20
4	FRONT WINDSCREEN MOULDING <i>New</i>	1	\$ 124.30	\$ 124.30
5	FRONT PILLAR RH <i>Rep</i>	1	\$ 381.69	\$ 381.69
6	FRONT DOOR VIEW MIRROR RH <i>New</i>	1	\$ 1,855.10	\$ 1,855.10
7	FRONT DOOR RH <i>Dented</i>	1	\$ 1,247.20	\$ 1,247.20
8	FRONT DOOR STEP GARNISH RH <i>New</i>	1	\$ 127.50	\$ 127.50
9	FRONT DOOR OUTER HANDLE RH <i>New</i>	1	\$ 148.70	\$ 148.70
10	FRONT DOOR OUTER HANDLE KEY LOCK RH <i>New</i>	1	\$ 128.50	\$ 128.50
11	FRONT DOOR BLACK STICKER RH <i>New</i>	1	\$ 59.60	\$ 59.60
12	FRONT DOOR OUTER MOULDING RH <i>New</i>	1	\$ 138.60	\$ 138.60
13	FRONT DOOR HINGE RH <i>3 New</i>	2	\$ 85.10	\$ 170.20
14	FRONT DOOR CHECKER RH <i>New</i>	1	\$ 183.80	\$ 183.80
15	FRONT DOOR WEATHER STRIP RH <i>cut</i>	1	\$ 170.10	\$ 170.10
16	FRONT DOOR FRAME WEATHER STRIP RH <i>New</i>	1	\$ 382.80	\$ 382.80
17	FRONT DOOR GLASS CHANNEL RH <i>Best</i>	1	\$ 124.90	\$ 124.90
18	FRONT DOOR INNER LOCK RH <i>Dented</i>	1	\$ 603.10	\$ 603.10
19	FRONT DOOR LOCK CATCH RH <i>New</i>	1	\$ 38.91	\$ 38.91
20	FRONT DOOR INNER TRIM BOARD RH <i>cracked</i>	1	\$ 746.50	\$ 746.50
21	FRONT DOOR REGULATOR RH <i>Dented</i>	1	\$ 317.20	\$ 317.20
22	FRONT DOOR POWER WINDOW MOTOR RH <i>New</i>	1	\$ 926.10	\$ 926.10
23	FRONT DOOR STOPPER RH <i>New</i>	1	\$ 24.50	\$ 24.50
24	FRONT DOOR SPEAKER RH <i>New</i>	1	\$ 288.70	\$ 288.70
25	CENTER PILLAR RH <i>Rep</i>	1	\$ 385.70	\$ 385.70

725

421

634

100/50

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLJ3947D
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 29.11.20
 TIME OF ACCIDENT : 10:25HRS

26	REAR DOOR RH <i>Repis</i>	1	\$ 1,248.01	\$ 1,248.01	+
27	REAR DOOR BLACK STICKER RH <i>new</i>	1	\$ 55.70	\$ 55.70	+
28	REAR DOOR HINGE RH <i>2</i>	2	\$ 85.10	\$ 170.20	+
29	REAR DOOR INNER LOCK RH	1	\$ 602.70	\$ 602.70	+
30	REAR DOOR INNER TRIM RH <i>new</i>	1	\$ 748.50	\$ 748.50	+
31	REAR DOOR WEATHER STRIP RH <i>new</i>	1	\$ 380.60	\$ 380.60	+
32	REAR DOOR OUTER STRIP RH	1	\$ 138.50	\$ 138.50	+

4075.70
3056.77

TOTAL PRICE \$ 12,937.21
 LESS 25% \$ 3,234.30
 SUB TOTAL PRICE \$ 9,702.91

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
2	FRONT CENTER GRILLE CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
3	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
4	FRONT FENDER UPPER CORNER GARNISH CLIP LH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	10
5	FRONT WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	+
6	FRONT WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00	+
7	FRONT PILLAR SEALANT RH	1	\$ 150.00	\$ 150.00	+
8	CENTER PILLAR INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
9	CENTER PILLAR SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
10	FRONT DOOR INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
11	FRONT DOOR STEP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
12	FRONT DOOR OUTER MOULDING CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
13	REAR DOOR INNER TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+

TOTAL \$ 1,040.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	700
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 80.00	30

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLJ3947D**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 29.11.20
 TIME OF ACCIDENT : 10:25HRS

5	REMOVE AND REFIX DASHBOARD	\$ 650.00	X
6	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	X
7	RESET RADIO SYSTEM	\$ 200.00	X
8	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	✓
9	TRANSFER REAR DOOR MECHANISM RH	\$ 80.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,240.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,742.91
 TOTAL LABOUR COST : \$ 5,240.00
 TOTAL REPAIR COST : \$ 15,982.91

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR
 MICHELLE
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian L
 1/5 30/11/20.

06 Days.

total: 4786.77.

1/5 381C

1670