



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 1989 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	? ✗
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	SSD ✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	SSD ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: <u>\$ 4,922.00</u>	

Car-in 24/12/2010

wip-59299.

Kiam/Kong

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Adrian

OK
4/12

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1989 M

MR. SK 7/12

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
SK MR	1 FRONT BUMPER <i>Rehd</i>	5	2,171.00	✓ 1736.80
	2 FRONT BUMPER FIXING PARTS <i>neu</i>	5	580.00	+
	3 FRONT BUMPER SECURING STRIP <i>? nn</i>	5	35.00	✓ X
	4 FRONT BUMPER GRILLE - CENTRE <i>neu</i>	5	194.00	+
	5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	5	208.00	+
	6 FRONT BUMPER AIR GUIDE - RH <i>neu</i>	5	62.00	+
SK MR	7 RADIATOR GRILLE <i>Carhd</i>	5	1,317.00	✓ 1053.60
	8 FRONT BUMPER AIR GUIDE GRILLE - RH <i>neu</i>	5	134.00	+
	9 FRONT BUMPER CARRIER <i>Best</i>	5	795.00	✓ 635.60
	10 FRONT BUMPER FOAM FILLER PIECE <i>Carhd</i>	5	123.00	✓ 98.40
	11 FRONT BUMPER GUIDE SECTION - RH <i>neu</i>	5	37.00	✓
	12 FRONT BUMPER TOP COVER <i>neu</i>	5	126.00	+
	13 CAUTION SIGN STICKER <i>? neu</i>	NEC 5	14.00	+
	14 AIRCON STICKER <i>? neu</i>	NEC 5	8.00	+
	15 LOCK CARRIER BRACKET <i>Carhd</i>	5	136.00	✓ 108.40
	16 LOCK CARRIER BRACKET SUPPORT - LH/RH <i>? nn 2</i>	5	56.00	✓ X
	17 HORN - RH LOW TONE <i>? neu</i>	5	124.00	+
	18 SPRING SHACKLE - RH	5	29.00	+
	19 FRONT PARKING AID SENSOR - INNER/OUTER <i>? 2</i>	5	484.00	+
	20 FRONT PARKING AID SEAL RING <i>? 4</i>	5	14.00	+
SUB TOTAL SPARE PARTS			\$	6,647.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1989 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 FRONT FENDER - RH	S	758.00	X
22 FRONT FENDER ATTACHMENT PARTS	S	200.00	X
23 FRONT FENDER CLOSING ELEMENT - RH	S	49.00	X
24 FRONT FENDER BRACKET - RH	S	35.00	X
25 DEFORMATION ELEMENT BRACKET - RH	S	49.00	X
26 WHEEL HOUSING LINER- RH	S	239.00	X
27 WHEEL HOUSING LINER ATTACHMENT PARTS	S	230.00	X
28 WHEEL SPOILER - RH	S	73.00	X
29 WHEEL SPOILER TRIM - RH	S	36.00	X
30 STONE CHIP GUARD - RH	S	50.00	+
31 TOP FENDER LEDGE COVER - UPPER	S	31.00	+
32 TOP FENDER LEDGE COVER - LOWER	S	23.00	+
33 LED HEADLIGHT - RH	S	7,693.00	X
34 LIFT CYLINDER - RH	S	208.00	X
35 LIFT CYLINDER CORRUGATED PIPE	S	92.00	X
36 RADIATOR AIR GUIDE - OUTER	S	28.00	X
37 RADIATOR AIR GUIDE - INNER	S	12.00	X
38 RADIATOR AIR GUIDE - UPPER	S	16.00	X
39 FRONT NO PLATE	S	60.00	X
40 SUNDRIES	S	250.00	X
TOTAL SPARE PARTS	:	\$ 16,779.00	
TOTAL LABOUR CHARGES	:	\$ 4,922.00	
GRAND TOTAL	:	\$ 21,701.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Resurveyed
Adrian Lim
23/12/20
H/S